


Lot 5 - FORD 4X2 TRACTOR



Colour: BLUE
Condition: NON RUNNER/ SCRATCHES ALL OVER THE BODY/ CAB SIDE WINDOWS ARE BROKEN/ ENGINE COVER IS RUSTED/ SEAT IS TORN
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Mileage: 770 HOURS

Lot 6 - FORD 4X2 TRACTOR



Colour: BLUE
Condition: NON RUNNER/ SCRATCHES ALL OVER THE BODY/ SOME RUSTMARKS / GRILL WITH PAINT PEELING/
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Mileage: 60 HOURS

Lot 7 - FORD 6610 4X2 TRACTOR



Colour: BLUE
Condition: NON RUNNER / SCRATCHES/ RUSTMARKS AND PAINT PEELING ALL OVER THE BODY/RIGHT CAB WINDOW BROKEN/ LEFT AND RIGHT DOORS ARE MISSING/
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
No_of_keys: NO KEYS

Lot 8 - MASSEY FERGUSON TRACTOR (SLASHER NOT INCLUDED)



Condition: NON RUNNER/ STRIPPED
LOCATION: CULLINAN - GAUTENG
Qty: 1
Mileage: 396.9 HOURS

Lot 9 - MASSEY FERGUSON 165 4X2 TRACTOR



Colour: RED
Condition: NON RUNNER/ SCRATCHES/ RUSTMARKS/ PAINT PEELING ALL OVER THE BODY/SOME DENTS ALL OVER THE BODY/
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Mileage: NOT VISIBLE

Lot 15 - 2014 MERCEDES BENZ AXOR 262B/33 TIP C/C



Colour: WHITE
Condition: NON RUNNER/ BODY HAS DENTS AND RUSTS/ NO KEY/ 1 HI-AB REMOTE/2 BATTERIES/ STILL IN GOOD CONDITION
LOCATION: OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 16 - 2006 HINO 57-450 AIR D/AXLE MECHANICAL HORSE



Colour: WHITE
Condition: NON RUNNER/SCRATCHES ON THE BODY
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS

Lot 17 - 2002 HINO PROFIA 45-350 D/AXLE MECHANICAL HORSE



Colour: WHITE
Condition: NON RUNNER/SCRATCHES ON THE BODY
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS

Lot 18 - VOLVO FE240 TRUCK WITH HYDRAULIC BEAVERTAIL RAMP



Condition: Runner/Work ready
LOCATION: DE OUDEBRUG STREET - WELLINGTON - WESTERN CAPE
Mileage: 800000

Lot 20 - SINGLE AXLE TIPPER TRAILER




Colour: RED
Condition: SCRATCHES/ RUSTED AND DENTED ALL OVER THE BODY
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
No_of_keys: NO KEYS

Lot 21 - 2008 SINGLE AXLE DRAWBAR TRAILER



Colour: YELLOW
Condition: SCRATCHES/ RUSTED/ DENTED ALL OVER
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
No_of_keys: NO KEYS

Lot 22 - SINGLE AXLE END TIP TRAILER



Colour: GREY
Condition: SCRATCHES ALL OVER THE BODY RUSTED PORTIONS AT THE BACK/
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Vin/serial No: AHA100A04K000012'

Lot 23 - 2008 SINGLE AXLE DRAWBAR TRAILER



Colour: YELLOW
Condition: SCRATCHES AND RUSTED ALL OVER THE BODY/ DENTED AND PAINT PEELING ALL OVER THE BODY
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Vin/serial No: AAH138691PHF11055'

Lot 24 - 2008 SINGLE AXLE DRAWBAR TRAILER



Colour: YELLOW
Condition: SCRATCHES AND RUSTED ALL OVER THE BODY/ DENTED AND PAINT PEELING ALL OVER THE BODY
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Vin/serial No: AAH183689PHF11055'

Lot 25 - POOLE SINGLE AXLE TRAILER DROPSIDE TRAILER



Colour: WHITE
Condition: SCRATCHES ON THE BODY/
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS

Lot 26 - MOREWEAR DROP SIDES SINGLE AXLE TRAILER



Condition: FAIR CONDITION
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO
Qty: 1
Vin/serial No: 9797'

Lot 27 - SELF MADE TRAILER



Colour: RED
Condition: RUST ON THE BODY/
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS

Lot 28 - VENTER TRAILER



Colour: RED
Condition: NO SPARE WHEEL /RIGHT SIDE FRONT FRAME DENTED/RUST MARKS NOTED ON THE BODY
LOCATION: MIDDELBURG MPUMALANGA
Qty: 1
Vin/serial No: VEL885519'

Lot 29 - VENTER BOX TRAILER (stripped)



Colour: WHITE
Condition: RUST MARK AND SCRATCHES ON THE BODY/DENT ON THE TOP FRONT PART/
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS

Lot 30 - 6M DOUBLE AXLE MOBILE CANTEEN



LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1

Lot 31 - 12M PARKHOME




LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1

Lot 32 - 6M PARKHOME



LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1

Lot 33 - 9M PARKHOME



LOCATION: SALVAGE YARD - NORTHAM - LIMPOPO
Qty: 1

Lot 34 - CHANGE HOUSE CONTAINER



Condition: INTERIOR IS DAMAGED/ FEW ROOFING SHEETS ARE DENTED
LOCATION: GOEDGEVONDEN PIT - OGIES - MPUMALANGA
Qty: 1

Lot 35 - CHANGE HOUSE CONTAINER



Condition: INTERIOR IS DAMAGED/ SOME WINDOWS ARE BROKEN
LOCATION: GOEDGEVONDEN PIT - OGIES - MPUMALANGA
Qty: 1

Lot 36 - CONTAINER RESTROOM



Condition: INTERIOR AND EXTERIOR IN A FAIR CONDITION
LOCATION: GOEDGEVONDEN PIT - OGIES - MPUMALANGA
Qty: 1

Lot 37 - CONTAINER



Condition: BROKEN WINDOWS/ MINOR DENTS AND RUST
LOCATION: GOEDGEVONDEN PIT - OGIES - MPUMALANGA
Qty: 1

Lot 38 - DIESEL GENERATOR



Condition: BURNT/ DAMAGED/ STRIPPED
LOCATION: GOEDGEVONDEN PIT - OGIES - MPUMALANGA
Qty: 1

Lot 39 - CONTAINER



Condition: BROKEN WINDOWS/
INTERIOR BOARDS ARE TORN/
MINOR DENTS AND RUSTS
LOCATION: GOEDGEVONDEN PIT
- OGIES - MPUMALANGA
Qty: 1

Lot 41 - MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/
CONTROL PANEL IS STRIPPED/
LOOSE WIRING 2 TYRES MISSING/
REAR COVER IS MISSING/ REAR
LIGHTS ARE MISSING/ ENGINE IS
STRIPPED/ BATTERY IS MISSING
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 42 - MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/ 1 TYRE
MISSING/ OIL LEAKS ON ENGINE/
REAR LIGHTS MISSING/ ENGINE IS
STRIPPED/ CONTROL PANRL IS
STRIPPED/ NO BATTERY
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 43 - MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/ 2
TYRES MISSING/ NO BATTERY/
TOWING HOOK IS MISSING/ LIGHTS
ARE MISSING/ PANEL IS STRIPPED/
ENGINE IS STRIPPED
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1
Vin/serial No: NO TAG'

Lot 44 - KNOTT GMBH KF20 MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/ SIDE
COVERS ARE MISSING/ RADIATOR
IS MISSING/ ENGINE IS STRIPPED/
BATTERY IS MISSING/ PANEL IS
STRIPPED/ ALTERNATOR IS
MISSING/ WIRING IS STRIPPED
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 45 - MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/
BATTERY IS MISSING/ LIGHTS ARE
MISSING/ RADIATOR IS LOOSE/
FAN IS MISSING/ ENGINE IS
STRIPPED
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 46 - KNOTT GMBH KF20 MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/
BATTERY IS MISSING/ SIDE
COVERS ARE DENTED/ CONTROL
PANEL IS STRIPPED
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 47 - KNOTT GMBH KF20 MOBILE LIGHTING PLANT



Colour: YELLOW
Condition: NON RUNNER/
BATTERY IS MISSING/ LIGHTS ARE
MISSING
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 48 - KNOTT GMBH KF20 MOBILE LIGHTING PLANT



Colour: WHITE
Condition: NON OPERATIONAL/
BATTERY IS MISSING/ ENGINE IS
STRIPPED/ PANEL IS STRIPPED/
RADIATOR IS MISSING
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 49 - 2023 MOBILE LIGHTING PLANT



Condition: NON OPERATIONAL/
BATTERY IS MISSING/ PANEL IS
STRIPPED
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 50 - 2023 ATLAS COPCO 852KG LIGHTING PLANT 2.2 KW



Condition: NON OPERATIONAL/
BATTERY IS MISSING/ 2 LIGHTS
MISSING

LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA

Qty: 1

Vin/serial No: ESF209244'

Lot 51 - 2023 ATLAS COPCO 852 KG MOBILE LIGHTING PLANT 2.2KW



Condition: NON OPERATIONAL/
PANEL IS DAMAGED/ BATTERY IS
MISSING/ RIGHT SIDE TYRE IS
MISSING/ FRONT COVER IS
MISSING/ OIL LEAKS ON ENGINE

LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA

Qty: 1

Vin/serial No: ESF209245'

Lot 52 - ATLAS COPCO MOBILE LIGHTING PLANT



Condition: NON OPERATIONAL/
WHEEL GUARDS BROKEN/
BATTERY IS MISSING

LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA

Qty: 1

Mileage: 07201HRS

Lot 53 - MOBILE LIGHTING PLANT (DAMAGED)



LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA

Qty: 1

Lot 65 - TOYOTA HINO 300 SERIES 614 PERSONNEL CARRIER *NEVER REGISTERED*



Colour: WHITE

Condition: NON-RUNNER
STRIPPED/BODY IS DENTED AND
RUSTED/ CARRIER WINDOWS ARE
BROKEN/ NO BATTERY/ NO RADIO/
DASHBOARD IS STRIPPED/ LOOSE
WIRING/ MIRRORS ARE BROKEN/
SEATS ARE TORN/ INSIDE
HANDLES ARE STRIPPED OFF/
GEAR LEVER IS MISSING/ ENGINE
IS STRIPPED/ OIL LEAKS/
RADIATOR IS STRIPPED OFF/
BUMPER IS STRIPPED OFF/ NON
RUNNER/ FUSE BOX IS STRIPPED/
IGNITION COVER IS REMOVED

LOCATION: KHUTHALA SALVAGE
YARD - OGIES - MPUMALANGA

Qty: 1

Mileage: NOT VISIBLE

Lot 66 - TOYOTA TRUCK *NEVER REGISTERED*



Colour: WHITE

Condition: NON-RUNNER
STRIPPED/ BUMPER IS STRIPPED/
LEFT FRONT LIGHT STRIPPED OFF/
BODY IS DENTED AND RUSTED/
DASHBOARD IS STRIPPED OFF/
CONTROLS ARE STRIPPED OFF/
FUSE BOX IS STRIPPED/ STEERING
WHEEL IS MISSING/ GEAR LEVER IS
MISSING/ WIRING IS STRIPPED/
CARRIER WINDOWS ARE BROKEN/
NO RADIO/ ENGINE IS STRIPPED/
RADIATOR IS STRIPPED

LOCATION: KHUTHALA SALVAGE
YARD - OGIES - MPUMALANGA

Qty: 1

Mileage: NOT VISIBLE

Lot 67 - TOYOTA PERSONNEL CARRIER *NEVER REGISTERED*



Colour: WHITE
Condition: NON-RUNNER
STRIPPED/ BODY IS DENTED AND
RUSTED/ BUMPER IS STRIPPED/
DRIVERS WINDOW IS BROKEN/
DASHBOARD IS STRIPPED/
IGNITION MECHANISM IS
STRIPPED/ NO RADIO/ GEAR LEVER
IS MISSING/ LIGHTS ARE BROKEN/
CONTROLS ARE STRIPPED OFF/
DRIVERS MIRROR IS MISSING
LOCATION: KHUTHALA SALVAGE
YARD - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 68 - TOYOTA HINO 611 300 PERSONNEL CARRIER *NEVER REGISTERED*



Colour: WHITE
Condition: NON RUNNER /
SCRATCHES AND RUST MARKS ALL
OVER THE BODY/ ENGINE
STRIPPED/ DASHBOARD STRIPPED/
WINDOWS BROKEN/ NO BATTERY/
NO RADIO
LOCATION: KHUTHALA SALVAGE
YARD - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 69 - 2017 TOYOTA HINO 23 SEATER PERSONNEL CARRIER



Colour: WHITE
Condition: NON
RUNNER/SCRATCHES AND RUST
MARKS NOTED ON THE BODY/ 2 X
12V BATTERIES/6 X STEEL
RIMS/RADIO MISSING
LOCATION: GOEDEGEVONDEN -
OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 70 - 2003 HINO 16-237 65 SEATED BUS



Colour: WHITE
Condition: NON RUNNER/ RUST
MARK AND SCRATCHES ALL OVER
THE BODY
LOCATION: DECLINE 1 -
NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS

Lot 71 - 1998 ISUZU N3500 D (FN) F/C C/C




Colour: WHITE
Condition: NON-RUNNER/ ENGINE
COMPLETE/ SCRATCHES/ DENTS/
PAINT FADING/ RUST VISIBLE/ FAIR
CONDITION
LOCATION: UPINGTON -
NORTHERN CAPE
Qty: 1
Mileage: 203605 KM

Lot 72 - 2013 MERCEDES-BENZ 519 CDI 22 SEATER SPRINTER



Colour: WHITE
Condition: NON
RUNNER/SCRATCHES AND RUST
MARKS NOTED ON THE BODY/
CUBBYHOLE DISMANTLED/ RADIO
FACE MISSING/NO KEY/ NO
BATTERY/BOTH LEFT AND RIGHT
WHEEL MISSING/DRIVERS DOOR
NOT CLOSING
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

**Lot 72A - 2013 MERCEDES-BENZ SPRINTER 515 CDI
F/C P/V**




Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/NO BATTERY/1 X KEY/SLIDING DOOR NOT CLOSING/2 X REAR WHEELS MISSING/1 X SEAT MISSING/ CUBBYHOLE IS MISSING
LOCATION: GLENCORE BOSCHMAN - WITBANK - MPUMALANGA
Qty: 1
Mileage: INVISIBLE

**Lot 73 - 2019 MERCEDES-BENZ SPRINTER 516 CDI
F/C P/V**



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS ALL OVER THE BODY/ MIRROR COVER MISSING/RADIO MISSING/ FRONT BUMPER LOOSE/1 X REAR RIGHT WHEEL MISSING /1 X BATTERY/1 X KEY/AIR-CONDITIONED
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 74 - MERCEDES BENZ 315 CDI SPRINTER



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES ALL OVER THE BODY/ FRONT BUMPER IS DISMANTLED/ THE WHOLE ENGINE AND DIFF ARE DISMANTLED AND STRIPPED IN PIECES// THE GRILL AS WELL IS DISMANTLED/
LOCATION: RUSTENBURG - NORTH WEST
Qty: 1
Mileage: NOT VISIBLE

**Lot 75 - 2011 VOLKSWAGEN CRAFTER 16 SEATER
MINI BUS**




Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/NO ENGINE/SOME FEW SPARES LYING INSIDE
LOCATION: MIDDELBURG MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

**Lot 76 - 2011 VOLKSWAGEN CRAFTER 15 SEATER
MINI BUS**



Colour: WHITE
Condition: RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/GEAR BOOT LOOSE/BONNET NOT OPENING/BOTH REAR CRAFTER AND TDI SIGNS DAMAGED/GEARBOX BEARING SOUND/BUMPER GRILL LOOSE/RIGHT FENDER SLIGHTLY DENTED/1 X BOLT ON THE PASSENGER SEAT MISSING/ RIGHT REAR SIGHT DENTED/1 X BATTERY 4 X STEEL RIMS/1 X RADIO/
LOCATION: MIDDELBURG MPUMALANGA
Qty: 1
Mileage: 222683

**Lot 99 - 2013 VOLKSWAGEN CADDY4 2.0TDi (81KW)
F/C P/V**




Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ NO SPARE WHEELS/DRIVERS SIDE ACCIDENT DAMAGED/1 X BATTERY /REAR RIMS DAMAGED / FRONT GRILL MISSING / RIGHT FRONT AND REAR LIGHTS MISSING /RIGHT MIRROR MISSING
LOCATION: GLENCORE BOSCHMAN - WITBANK - MPUMALANGA
Qty: 1
Mileage: INVISIBLE

Lot 100 - 2006 TOYOTA QUANTUM 2.7 F/C P/V



Colour: WHITE
Condition: NON-RUNNER/ ENGINE COMPLETE/ SCRATCHES/ DENTS/ RUST VISIBLE
LOCATION: SPRINGBOK - NORTHERN CAPE
Qty: 1
Mileage: 350621 KM

Lot 101 - 2011 TOYOTA QUANTUM 2.7 10 SEAT



Colour: WHITE
Condition: NON-RUNNER/ ENGINE STRIPPED/ STARTER DISMANTLED/ SCRATCHES/ DENTS/ RUST VISIBLE/ NO WIPER BLADES/ TIRES INSIDE EXCLUDED
LOCATION: UPINGTON - NORTHERN CAPE
Qty: 1
Mileage: 318419 KM

**Lot 102 - 2016 NISSAN NV350 2.5 16 SEAT
IMPENDULO**



Colour: WHITE
Condition: NON-RUNNER/
ACCIDENT DAMAGE/ TWO WHEELS
DAMAGED/ WINDOW DAMAGED/
RUST VISIBLE
LOCATION: KURUMAN -
NORTHERN CAPE
Qty: 1
Mileage: 84337 KM

Lot 109 - 2018 TOYOTA QUANTUM



Condition: NON-RUNNER/ ENGINE
COMPLETE/ BATTERY INCLUDED/
MINOR SCRATCHES AND DENTS/
CUBBY HOLE DISMANTLED/ GOOD
CONDITION
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE
Qty: 1
Vin/serial No:
JTFSS23P900170212'
Reg_no: CRY975NC

**Lot 120 - 2014 FORD RANGER 2.2TDCi XL P/U
SUP/CAB**



Colour: WHITE
Condition: NON-RUNNER/
GEARBOX FAULTY AND
DISMANTLED/ PAINT PEELING/
RUST VISIBLE/ LEFT PASSENGER
DOOR FAULTY/ MINOR SCRATCHES
AND DENTS/ FAIR CONDITION
LOCATION: SPRINGBOK -
NORTHERN CAPE
Qty: 1
Mileage: 274740 KM

**Lot 121 - 2010 2011 PER NATIS FORDRANGER
3.0TDCi XLT 4X4 P/U SUP/CAB**



Colour: CHARCOAL
Condition: NON-RUNNER/ ENGINE
STRIPPED AND DISMANTLED/
GEARBOX VISIBLE/ PAINT FADING/
LEFT TAIL LIGHT DAMAGED/
SCRATCHES/ DENTS/ RUST VISIBLE
LOCATION: KURUMAN -
NORTHERN CAPE
Qty: 1
Mileage: 246496 KM

**Lot 122 - 2012 TOYOTA HILUX 2.5 D-4D SRX 4X4
P/U S/C**



Colour: WHITE
Condition: NON RUNNER/
SCRATCHES AND RUST MARKS
NOTED ON THE BODY/ RIGHT TAIL
LIGHT BROKEN/CUBBYHOLE
DISMANTLED/NO RADIO/NO
BATTERY/ FRONT BUMPER
LOOSE/LEFT FRONT TYRE
DAMAGED
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

**Lot 123 - 2012 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C**




Colour: WHITE
Condition: NON RUNNER/
SCRATCHES AND RUST MARKS
NOTED ON THE BODY/
CUBBYHOLE NOT CLOSING/TIMING
CHAIN LOOSE/FUSE BOX
STRIPPED/ PRIME PUMP LOOSE/NO
INJECTORS/ FAN BELT LOOSE/NO
BATTERY /1 X RADIO/ 1X KEY/4 X
STEEL RIMS
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 124 - 2012 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C




Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ INJECTORS MISSING/ OIL LEAKS NOTED/INJECTORS COMPUTER BOX MISSING/BATTERY MISSING/ TEPPE COVER LOOSE/RADIO MISSING/4 X STEEL RIMS/BONNET CABLE IS LOOSE/ BOTH FRONT TYRES ARE FLAT
LOCATION: GLENCORE BOSCHMAN - WITBANK - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 125 - 2012 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C




Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS ALL OVER THE BODY/ INJECTORS MISSING/ TEPPE COVER LOOSE/COMPUTER BOX MISSING/4 X STEEL TMS/
LOCATION: GLENCORE BOSCHMAN - WITBANK - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 126 - 2012 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C



Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/ IGNITION COVER STRIPPED/OIL LEAKS SLIGHTLY NOTED/ FUSE BOX STRIPPED/ NO BATTERY/INJECTORS COMPUTER BOX MISSING/FRONT BUMPER DAMAGED/4 X STEEL RIMS/RIGHT HEAD LIGHT BROKEN/ RIGHT FENDER LOOSE/INDICATOR LIGHTS MISSING / NUMBER PLATE IS BUMPED
LOCATION: GLENCORE BOSCHMAN - WITBANK - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 127 - 2014 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C




Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/ LOADING BIN DAMAGED/ TAIL GATE SLIGHTLY DENTED/NO COMPUTER BOX/IGNITION STRIPPED/GEAR LEAVER BOOT LOOSE/NO BATTERY/FUSE BOX STRIPPED/BONNET LOOSE/FRONT BUMPER LOOSE/RIGHT FENDER LOOSE
LOCATION: GLENCORE BOSCHMAN - WITBANK - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 128 - 2012 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C




Colour: WHITE
Condition: NON RUNNER/
SCRATCHES AND RUST MARKS
NOTED ON THE BODY/NO ENGINE/
NO BATTERY/ BONNET
LOOSE/BUMPER CRILL
MISSING/DASHBOARD BDLY
STRIPPED/NO COMPUTER
BOX/GEAR LEAVER BOOT
MISSING/1 X RADIO/4 X STEEL
RIMS/LEFT TAIL LIGHT
BROKEN/RADIATOR MISSING/ FAN
MISSING
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 129 - 2013 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C




Colour: WHITE
Condition: NON RUNNER/
SCRATCHES AND RUST MARKS ALL
OVER THE BODY/DASHBOARD
STRIPPED/ SPEEDOMETER
MISSING/RADIO MISSING WIRING
LOOSE/REAR PASSENGER SEATS
CONVERTED/ FUSE BOX STRIPPED/
NO BATTERY/ FRONTEND BUMPER
LOOSE/4 X STEEL RIMS/INJECTORS
COMPUTER BOX MISSING/ POWER
STEERING FLUIT BOTTLE CAP
MISSING/ LEFT MIRROR
MISSING /REAR LIGHTS
MISSING /FRONT TYRE
DAMAGED /GEAR LEVER KNOP
MISSING
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 130 - 2013 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C



Colour: WHITE
Condition: NON
RUNNER/SCRATCHES AND RUST
MARKS ALL OVER THE BODY/
BONNET NO CLOSING/CRILL
MISSING/FRONT BUMPER
LOOSE/NO ENGINE/NO BATTERY/
CUBBYHOLE IS MISSING /
TAILGATE HANDLE IS MISSING /
TAILGATE NOT CLOSING /
INDICATOR LIGHTS MISSING
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 131 - 2010 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C



Colour: WHITE
Condition: NON
RUNNER/SCRATCHES AND RUST
MARKS ALL OVER THE
BODY/WIRING LOOSE/INJECTORS
MISSING/INJECTORS COMPUTER
BOX MISSING/TEPPET COVER
MISSING/ FAN BELT
MISSING/BATTERY/ FRONT
BUMPER LOOSE/IGNITION
STRIPPED/ STEERING WHEEL
STRIPPED//FRONT WHEELS
MISSING/CUBBYHOLE IS LOOSE /
LEFT MIRROR MISSING / TAILGATE
NOT CLOSING / DRIVER SEAT
COVER TORN
LOCATION: GLENCORE
BOSCHMAN - WITBANK -
MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 132 - 2023 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ DASHBOARD STRIPPED/ RADIO MISSING/ GEAR LEAVER BOOT STRIPPED/ CUBBYHOLE DISMANTLED/ COMPUTER BOX MISSING DRIVERS SEAT LOOSE/ DRIVER DOOR NOT OPENING/ ALTERNATOR MISSING/ THROTTLE BODY MISSING/1 X 12V BATTERY MISSING/ CAM BELT LOOSE/RIGHT MIRROR MISSING
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VIISIBLE

Lot 133 - 2021 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4 A/T P/U D/C



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ DRIVERS DOOR PANEL LOOSE/DRIVERS SIDE MIRROR MISSING/LEFT FENDER DENTED/LEFT TAIL LIGHT BROKEN/1 X RADIO/1 X 12V BATTERY/ 4 X STEEL RIMS / FAN BELT IS LOOSE
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 134 - 2020 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES & RUSTMARKS NOTED ON THE BODY/ STEERING WHEEL AIRBAG MISSING/ DASHBOARD STRIPPED/1 X 12V BATTERY/ 4 X STEEL RIMS/RADIO IS MISSING / DOOR PANEL LOOSE
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 135 - 2020 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/ RADIO MISSING/ DASHBOARD STRIPPED/ 1 X 12V BATTERY/2 X TAIL LIGHTS MISSING/4 X STEEL RIMS/ OIL CAP IS MISSING
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 136 - 2020 TOYOTA HILUX 2.4GD6 4X4 S/C WITH TOOL BOX



Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/ 1 X BATTERY/RADIO MISSING/ DASHBOARD STRIPPED/ 4 X STEEL RIMS/FRONT LEFT TYRE DAMAGED
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 137 - 2020 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U S/C WITH TOOL BOX



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ 1 X 12V BATTERY/ RADIO MISSING/4 X STEEL RIMS
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 139 - 2022 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4
A/T P/U D/C



Colour: WHITE
Condition: NON
RUNNER/SCRATCHES AND RUST
MARKS NOTED ON THE BODY/1 X
RADIO/ 4 X STEEL RIMS/ FUSE BOX
SLIGHTLY STRIPPED/1 X 12V
BATTERY
LOCATION: GOEDEGEVONDEN -
OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 140 - 2021 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4
A/T P/U D/C



Colour: WHITE
Condition: NON
RUNNER/SCRATCHES AND RUST
MARKS NOTED ON THE BODY/ FAN
BELT MISSING/ ALTERNATOR
MISSING/TURBO MISSING/
BATTERY MISSING/ FUSE BOX
STRIPPED/ PRIME PUMP
DISMANTLED/ INJECTORS
MISSING/RADIATOR PIPE
MISSING/RADIO MISSING/ 4 X
STEEL RIMS
LOCATION: GOEDEGEVONDEN -
OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 141 - 2023 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4
P/U D/C



Colour: WHITE
Condition: NON RUNNER
SCRATCHES AND RUST MARKS
NOTED ON THE BODY/ 1 X 12V
BATTERY/ IGNITION COVER
STRIPPED/ RADIO MISSING/
DASHBOARD STRIPPED/
CUBBYHOLE DISMANTLED/ 4 X
STEEL RIMS
LOCATION: GOEDEGEVONDEN -
OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 142 - 2013 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U
D/C



Colour: WHITE
Condition: NON RUNNER/ NO
KEYS/ NO SPARE WHEEL/ BODY
RUSTED AND SCRATCHED/ 1X
RADIO/ NO CUBBY HOLE/
INTERIOR FUSE COVERS MISSING/
RIGHT REAR DOOR WINDOW
BROKEN/ NO GRILL/ NO BATTERY/
NO INJECTORS/ NO FUSES/ 4X
STEEL RIMS/ ENGINE TOP COVER
MISSING/ NO ALTERNATOR/
WATER PIPES DISMANTLED/ LEFT
FRONT WHEEL DAMAGED/ BOTH
REAR LIGHTS MISSING/ FRONT
GRILL MISSING / 2X TAILGATE
LIGHTS MISSING
LOCATION: GOEDEGEVONDEN -
OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 143 - 2013 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ SOME WIRING CUT OFF/ FAN BELT MISSING/INJECTORS MISSING/ TAPPET COVER MISSING/ STARTER MISSING/FUSE BOX STRIPPED/ BATTERY MISSING/ALTERNATOR MISSING/ PRIME PUMP MISSING/ CLUSTER MISSING/RADIO MISSING/ COMPUTER BOX MISSING/ MAIN WINDOW MECHANISM MISSING/FRONT LEFT PASSENGER DOOR PANEL LOOSE
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 144 - 2018 TOYOTA HILUX 2.4 GD-6 SRX 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/ FUSES MISSING/ 1X BATTERY/ FRONT BUMPER DAMAGED/ 2X STEEL RIMS/ 2X MAG RIMS/ ROOF RUSTED / GEARBOX COVERS DISMANTLED/ 1X RADIO/ FLOOR RUBBERIZED/ BONNET CABLE BROKEN/ SEATS COVERS TORN/ NO SPARE WHEEL/ KEYS DOESN'T OPEN DOORS/DASHBOARD STRIPPED
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 145 - 2019 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/ SCRATCHES AND RUST MARKS NOTED ON THE BODY/ FUSE BOX STRIPPED/ 1 X BELT PULLEY MISSING/ FAN BELT LOOSE/1 X 12V BATTERY MISSING/ INJECTORS COMPUTER BOX MISSING/ 4 X STEEL RIMS/1 X RADIO MISSING/DIESEL CAP MISSING
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

Lot 146 - 2019 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U D/C



Colour: WHITE
Condition: NON RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/ CUBBYHOLE DISMANTLED/1 X BATTERY/ 1 X KEY/RADIO IS MISSING
LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

**Lot 147 - 2022 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4
A/T P/U D/C**



Colour: WHITE
Condition: NON RUNNER/
 SCRATCHES AND RUST MARKS
 NOTED ON THE BODY/ RADIATOR
 MISSING/ RADIATOR FAN MISSING/
 BATTERY MISSING/ PRIME PUMP
 MISSING/ INJECTORS MISSING/ AIR
 FLOW METER MISSING/ FAN BELT
 MISSING/ RADIO MISSING/
 DASHBOARD STRIPPED/ CLUSTER
 COVER MISSING/GEAR LEVER
 BOOT MISSING/DRIVERS DOOR
 NOT OPENING /LEFT PASSENGER
 DOOR WINDOW GLASS
 DISMANTLED/ COMPUTER BOX
 MISSING TAIL GATE
 DISMANTLED/ENGINE IS STRIPPED
 APART / ALTERNATOR IS MISSING /
 RADIATOR PIPES MISSING /
 PULLEYS ARE MISSING
LOCATION: GOEDEGEVONDEN -
 OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

**Lot 148 - 2022 TOYOTA HILUX 2.4 GD-6 RAIDER 4X4
A/T P/U D/C**



Colour: WHITE
Condition: NON
 RUNNER/SCRATCHES AND RUST
 MARKS NOTED ON THE BODY/
 ENGINE MISSING/ FUSE BOX
 STRIPPED/ BATTERY MISSING/
 CLUSTER MISSING/RADIO
 MISSING/DASHBOARD STRIPPED/
 MAIN WINDOW MECHANISM
 MISSING/ COMPUTER BOX
 MISSING/ GEAR LEVER BOOT
 MISSING/ 4 X STEEL RIMS/
 STEERING WHEEL AIRBAG
 MISSING/IGNITION STRIPPED
LOCATION: GOEDEGEVONDEN -
 OGIES - MPUMALANGA
Qty: 1
Mileage: NOT VISIBLE

**Lot 148A - 2011 TOYOTA HILUX 4X4 SINGLE CAB
BAKKIE D4D**



Colour: WHITE
Condition: RUNNER/ MINOR
 DENTS AND STRATCHES NOTED
 ON THE BODY/ 1 RADIO/ TAILGATE
 IS DENTED
LOCATION: OGIES -
 MPUMALANGA
Qty: 1
Mileage: 76243

Lot 149 - TOYOTA HILUX SINGE CAB



Condition: NON RUNNER
LOCATION: DECLINE 1 -
 NORTHAM - LIMPOPO
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NOT VISIBLE '

Lot 150 - TOYOTA HILUX SINGE CAB




LOCATION: DECLINE 1 -
 NORTHAM - LIMPOPO
Qty: 1

Lot 151 - FORD RANGER DOUBLE CAB



LOCATION: DECLINE 1 -
 NORTHAM - LIMPOPO
Qty: 1

Lot 152 - FORD RANGER 4X4 DOUBLE CAB



Colour: WHITE
Condition: NON RUNNER
 /SCRATCHES ON THE BODY/NO
 KEY/LOCKED
LOCATION: DECLINE 1 -
 NORTHAM - LIMPOPO
Qty: 1
Mileage: NOT VISIBLE

**Lot 153 - 2001 TOYOTA HILUX 3.0D 4X4 SINGLE
CAB**



Colour: WHITE
Condition: NON RUNNER/RUST
 MARK AND SCRATCHES ALL OVER
 THE BODY/NO KEYS
LOCATION: DECLINE 1 -
 NORTHAM - LIMPOPO
Qty: 1
Mileage: NOT VISIBLE

Lot 154 - ISUZU 4X4 AMBULANCE



Colour: WHITE
Condition: NON RUNNER/
INTERIOR STRIPPED/ NO
BATTERY/ RUST MARK AND
SCRATCHES ALL OVER THE BODY/
DOOR HANDLE DAMAGED/
LOCATION: 4 SOUTH SHAFT -
NORTHAM - LIMPOPO
No_of_keys: NO KEY
Vin/serial No:
ADNTFS77H2B186963'

Lot 155 - TOYOTA HILUX S/C P/U



Condition: NON RUNNER /
ENGINE BAY STRIPPED / LIGHTS
STRIPPED / RUSTED / INTERIOR
STRIPPED / SEATS TORN / TIRES
FLAT / SPARES ON BACK
LOCATION: CULLINAN - GAUTENG
Qty: 1
Mileage: 226888KM
Reg_no: HVX857GP

Lot 156 - TOYOTA 4X4 LANDCRUISER S/C P/U



Condition: NON RUNNER
STRIPPED / RUSTED
LOCATION: CULLINAN - GAUTENG
Qty: 1

Lot 157 - TOYOTA 4X4 LANDCRUISER S/C P/U




Condition: NON RUNNER
STRIPPED / WINDSHIELD BROKEN /
FRONT BUMPER ON THE BACK
LOCATION: CULLINAN - GAUTENG
Qty: 1
Vin/serial No:
JTLEB71JX07111911'

Lot 158 - TOYOTA 4X4 LANDCRUISER S/C P/U



Condition: NON RUNNER
STRIPPED / SEATS TORN
LOCATION: CULLINAN - GAUTENG
Qty: 1

Lot 159 - TOYOTA 4X4 LANDCRUISER S/C P/U



Condition: NON RUNNER
STRIPPED / WINDSHIELD BROKEN
LOCATION: CULLINAN - GAUTENG
Qty: 1

Lot 160 - TOYOTA HILUX S/C P/U



Condition: RUSTED / SCRATCHED
/ SEATS TORN / NO BATTERY /
ENGINE SEEMS COMPLETE
LOCATION: CULLINAN - GAUTENG
Qty: 1
Vin/serial No:
AHTCR32G808013341'

Lot 161 - TOYOTA HILUX S/C P/U



Condition: FRONT WHEEL
MISSING / FRONT SIDE FENDER
RUSTED AND DAMAGED / WHEEL
FLAT / INTERIOR STRIPPED / NO
SEATS / TAILGATE MISSING /
RUSTED ALL OVER THE BODY
LOCATION: CULLINAN - GAUTENG
Qty: 1
Vin/serial No:
AHTDR22G005518824'

Lot 162 - 2008 TOYOTA HILUX 2.5D-4D SRX 4X4 P/U S/C



Colour: WHITE
Condition: RUNNER/ REAR
BUMPER SCRATCHED/ 1X
BATTERY/ 1X RADIO/ 4X STEEL
RIMS/ FRONT BUMPER LOOSE /
CLUSTER REPLACED
LOCATION: WATER RECLAMATION
PLANT - MIDDELBURG -
MPUMALANGA
Qty: 1
Mileage: 21015 KM

Lot 163 - 2003 TOYOTA HILUX 2400D LWB SINGLE CAB



Colour: WHITE
Condition: NON RUNNER/RUST
MARK AND SCRATCHES ALL OVER
THE BODY/ NO KEYS/LOCKED/
LOCATION: DECLINE 1 -
NORTHAM - LIMPOPO
Qty: 1
Mileage: NOT VISIBLE

Lot 168 - 2017 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U D/C *SCRAPPED*



Condition: NON-RUNNER
COMPLETE/ DENTS/ SCRATCHES/
DASHBOARD STRIPPED/ TWO
WHEELS FLAT/ BOTH TAIL LIGHTS
MISSING/ RUST VISIBLE/ BATTERY
INCLUDED

LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Qty: 1

Lot 169 - 2015 FORD RANGER RANGER 2.2TDCi XL PLUS 4X4 P/U C/C *SCRAPPED*



Condition: NON-RUNNER
COMPLETE/ DENTS/ SCRATCHES/
FRONT BUMPER SLIGHTLY
DAMAGED/ RUST VISIBLE/
BATTERY INCLUDED

LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Qty: 1

Lot 170 - 2015 FORD RANGER



Condition: NON-RUNNER/ ENGINE
STRIPPED/ NO BATTERY/ LEFT
FENDER MISSING/ SCRATCHES/
DENTS/ LEFT REAR DOOR HANDLE
MISSING/ REAR BADGE MISSING/
TOW BAR REMOVED/ RUST VISIBLE

LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Qty: 1

Vin/serial No:
AFAPXXMJ2PFS89559'

Reg_no: CMF450NC

Lot 171 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U C/C



Condition: NON-RUNNER/ ENGINE
COMPLETE/ BATTERY INCLUDED/
SCRATCHES/ DENTS/ RUST
VISIBLE/ DRIVER SEAT TORN/
GEAR LEVER STRIPPED/ ONE
WHEEL FLAT

LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Qty: 1

Vin/serial No:
AFAPXXMJ2PFS00484'

Reg_no: CMF447NC

Lot 172 - 2020 TOYOTA HILUX 2.4 GD-6 SR 4X4 P/U D/C



Condition: NON-RUNNER/ ENGINE
COMPLETE/ BATTERY INCLUDED/
SCRATCHES/ DENTS/ RUST
VISIBLE/ DRIVER SEAT TORN/
GEAR LEVER STRIPPED/ ONE
WHEEL FLAT

LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Qty: 1

Vin/serial No:
AHTKB3CDX02633647'

Reg_no: CWN679NC

Lot 173 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U D/C *SCRAPPED*



Condition: NON-RUNNER
COMPLETE/ DENTS/ SCRATCHES/
DRIVER WINDOW DAMAGED/
FRONT DRIVER AND PASSENGER
SEATS TORN/ RUST VISIBLE/ ONE
WHEEL FLAT/ BATTERY TERMINALS
MISSING/ ONE DOOR HANDLE
MISSING

LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Qty: 1

Mileage: NOT VISIBLE

No_of_keys: 1

**Lot 174 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4
P/U D/C *SCRAPPED***




Condition: NON-RUNNER
COMPLETE/ DENTS/ SCRATCHES/
DRIVER SEAT TORN/ DASHBOARD
SLIGHTLY STRIPPED/ FRONT DOOR
PANELS SLIGHTLY STRIPPED/
CUBBY HOLE DISMANTLED/ LEFT
FRONT DOOR HANDLE MISSING/
BOTH SIDE STEPS DENTED AND
COVERS MISSING/ ONE BATTERY
TERMINAL MISSING/ PIECE OF
FRONT GRILL SLIGHTLY DAMAGED
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: 1

**Lot 175 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4
P/U D/C *SCRAPPED***



Condition: NON-RUNNER
COMPLETE/ DENTS/ SCRATCHES/
DRIVER SEAT TORN/ CUBBY HOLE
DISMANTLED/ GEAR LEVER
MISSING/LEFT FRONT DOOR PANEL
SLIGHTLY STRIPPED/ FRONT
BUMPER DAMAGED AND
MISALIGNED/ LEFT REAR DOOR
PANEL MISSING/ NO BATTERY/
FEW COVERS MISSING
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: 1

Lot 190 - 2017 TOYOTA COROLLA 1.6 ESTEEM



Colour: WHITE
Condition: RUNNER/ GOOD
CONDITION
LOCATION: RUSTENBURG -
NORTH WEST
Qty: 1
Mileage: 132710

Lot 191 - 2017 TOYOTA COROLLA 1.6 ESTEEM



Colour: WHITE
Condition: RUNNER/ GOOD
CONDITION
LOCATION: RUSTENBURG -
NORTH WEST
Qty: 1
Mileage: 60792

**Lot 192 - 2008 2009 PER NATIS FORD FOCUS 2.0 Si
A/T**



Colour: WHITE
Condition: NON RUNNER/ ENGINE
STRIPPED AND DISMANTLED/
SCRATCHES/ DENTS/ CHIPMARKS
ON PAINT
LOCATION: SPRINGBOK -
NORTHERN CAPE
Qty: 1
Mileage: 396482 KM

**Lot 193 - 2010 2011 PER NATIS FORD FOCUS 1.8 Si
5Dr**



Colour: WHITE
Condition: NON-RUNNER/ ENGINE
STRIPPED/ GEARBOX STRIPPED/
MINOR SCRATCHES AND DENTS
LOCATION: SPRINGBOK -
NORTHERN CAPE
Qty: 1
Mileage: 289943 KM

Lot 194 - 2009 CHEVROLET OPTRA 1.6 L




Colour: WHITE
Condition: NON-RUNNER/ ENGINE
STRIPPED AND DISMANTLED/
GEARBOX STRIPPED AND
DISMANTLED/ BOTH TAIL LIGHTS
DAMAGED/ BIG DENT ON ROOF/
MINOR SCRATCHES AND DENTS
LOCATION: SPRINGBOK -
NORTHERN CAPE
Qty: 1
Mileage: 352712 KM

Lot 195 - 2009 NISSAN TIIDA 1.6 VISIA (H30)




Colour: WHITE
Condition: NON-RUNNER/ENGINE
COMPLETE/ MINOR ACCIDENT
DAMAGED/ BUMPER LOOSE/ GRILL
LOOSE/ SCRATCHES/ DENTS/ RUST
VISIBLE/ ONE TIRE DAMAGED/
BOTH SIDE MIRRORS MISSING/
RIGHT TAIL LIGHT DAMAGED
LOCATION: KURUMAN -
NORTHERN CAPE
Qty: 1
Mileage: 275218 KM

Lot 210 - TRUCK ENGINE




LOCATION: RUSTENBURG - NORTH WEST
Qty: 1

Lot 211 - BAKKIE ENGINE



LOCATION: RUSTENBURG - NORTH WEST
Qty: 1

Lot 212 - ISUZU DIESEL ENGINE



LOCATION: RUSTENBURG - NORTH WEST
Qty: 1

Lot 213 - DEUTZ DIESEL MINING ENGINES



LOCATION: CULLINAN - GAUTENG
Qty: 1

Lot 214 - DOOSAN ENGINES



LOCATION: CULLINAN - GAUTENG
Qty: 3

Lot 215 - TOYOTA HILUX GD6 LOADING BIN



LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1

Lot 216 - TOYOTA HILUX GD6 LOADING BIN



LOCATION: GOEDEGEVONDEN - OGIES - MPUMALANGA
Qty: 1

Lot 217 - LOT ASSORTED TOYOTA SPARES(EXCLUDING THE BIN)




LOCATION: GOEDGEVONDEN SALVAGE YARD - OGIES - MPUMALANGA
Qty: 1

Lot 218 - LOT ASSORTED TOYOTA AND BOBCAT SPARES(EXCLUDING THE BIN)



LOCATION: GOEDGEVONDEN SALVAGE YARD - OGIES - MPUMALANGA
Qty: 1

Lot 219 - TOYOTA D4D DENSE RADIATOR



Condition: IN GOOD CONDITION
LOCATION: GOEDGEVONDEN SALVAGE YARD - OGIES - MPUMALANGA
Qty: 1

Lot 220 - TRAILER LAMP BRACKET 3 HOLE



LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 14

Lot 221 - LOT ASSORTED FLOOR JACKS (3) AND MOBILE TRESTLES (2)



LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 222 - LOT ASSORTED TOYOTA CLUTCH AND BRAKE CABLES



Condition: IN GOOD CONDITION
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 223 - EASY AUTO RADIATORS



LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 2

Lot 224 - 25 TOYOTA D4D PROPSHAFTS AND 10 TOYOTA FRONT DRIVE SHAFTS



Condition: RUSTED/ FAIR
CONDITION
LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 25

Lot 225 - LOT ASSORTED SUSPENSION SPARES/ DIFFS/ AXLE/ GEARBOX



LOCATION: GOEDGEVONDEN
SALVAGE YARD - OGIES -
MPUMALANGA
Qty: 1

Lot 226 - FORD RANGER T6 3.2 SPARES




Condition: N/A
LOCATION: MIDDELBURG
MPUMALANGA
Qty: 1

Lot 227 - PERSONNEL CARRIER




LOCATION: NORTHAM - LIMPOPO
Qty: 1

Lot 228 - ASSORTED CANOPIES FOR HILUX SINGLE CAB



LOCATION: DECLINE 1 -
NORTHAM - LIMPOPO
Qty: 2

Lot 229 - LOT ASSORTED BAKKIE SPARES



LOCATION: DECLINE 1 -
NORTHAM - LIMPOPO
Qty: 1

Lot 230 - ENGINE SPARES AND HANDLES



LOCATION: MAIN STORES -
NORTHAM - LIMPOPO
Qty: 1

Lot 231 - TRACTOR TYRES (16.9 - 28)



LOCATION: RUSTENBURG -
NORTH WEST
Qty: 2

Lot 232 - ASSORTED TYRES (7.00 X 16)(295/65R X 17)(5.00 X 15)(10.00 X 16)



LOCATION: RUSTENBURG -
NORTH WEST
Qty: 22

Lot 233 - TYRES (15-19.5)



LOCATION: RUSTENBURG -
NORTH WEST
Qty: 4

Lot 234 - ASSORTED TYRES 5 WITH RIMS AND 3 WITHOUT RIMS(20.5R25)(18.4/15-34)(16.0/70-20)



LOCATION: RUSTENBURG -
NORTH WEST
Qty: 8

Lot 235 - BUMPER



LOCATION: RUSTENBURG -
NORTH WEST
Qty: 1