


**October Mining Auction 1 :
Small, Medium & Commercial
Fleet and Related Spares** All
lots are sold **STC**

Venue: **Northam, Limpopo**

Tuesday, 27 October @ 10h00

Lot 1 - SUBJECT TO CONFIRMATION PERIOD



Lot 5 - START OF THARISA MINERALS ASSETS



Lot 6 - 2021 FUSO CANTER VS FG6-136 SERVICE TRUCK



Colour: White
Condition: RUNNER/ MACHINE HAS COMPRESSOR/ OILS AND COOLANT TANKS
Qty: 1
Mileage: 11900
No_of_keys: 1

Lot 7 - 2021 FUSO CANTER VS FG6-136 SERVICE TRUCK



Colour: White
Condition: RUNNER/ INCLUDING COMPRESSOR/ OILS AND COOLANT TANKS
Qty: 1
Mileage: 10954
No_of_keys: 1

Lot 8 - 2019 TOYOTA HILUX 2.4 GD-6 SR 4X4 DOUBLE CAB



Colour: WHITE
Condition: RUNNER/ CUBBY HOLE DISMANTLED/ STEERING COVER MISSING AND DISMANTLED/ DENTED & SCRATCHED ALL ROUND/ SEATS ARE TORN
Qty: 1
Mileage: 210 541KM
Vin/serial No: AHTKB3CD702622900'

Lot 9 - 2021 TOYOTA HILUX 2.4 GD-6 SR 4X4 DOUBLE CAB



Colour: WHITE
Condition: RUNNER/ INTERIOR FAIR/ WHEELS ARE FLAT/ ENGINE IS COMPLETE
Qty: 1
Mileage: 277 722KM
Vin/serial No: AHTKB3CD302634591'

Lot 10 - 2021 TOYOTA HILUX 2.4 GD-6 SR 4X4 DOUBLE CAB



Colour: WHITE
Condition: RUNNER/ OIL LEAKS ALL ROUND/ FAIR CONDITION/ FAIR INTERIOR/
Qty: 1
Mileage: 176 171KM
Vin/serial No: AHTKB3CD702639602'

Lot 11 - 2016 TOYOTA HILUX 2.4 GD-6 SR 4X4 DOUBLE CAB



Colour: WHITE
Condition: NON RUNNER/ LOCKED/ COULD NOT BE TESTED/ REAR FENDER HAS BEEN DENTED/
Qty: 1
Mileage: NOT VISIBLE
Vin/serial No: AHTKB8CD102961519'

Lot 12 - REAR BED TUB WELLBODY ASSEMBLY FOR TOYOTA LANDCRUISER



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 13 - REAR BED TUB WELLBODY ASSEMBLY FOR TOYOTA LANDCRUISER



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 14 - REAR BED TUB WELLBODY ASSEMBLY FOR TOYOTA LANDCRUISER



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 15 - REAR BED TUB WELLBODY ASSEMBLY FOR TOYOTA LANDCRUISER



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 16 - REAR BED TUB WELLBODY ASSEMBLY FOR TOYOTA LANDCRUISER



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 17 - TOYOTA LANDCRUISER BODY & SUSPENSION SPARES



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 25 - START OF SIYANDA BAKGATLA ASSETS



Lot 26 - 2006 HINO 57-450 AIR D/AXLE MECHANICAL HORSE



Colour: WHITE
Condition: NON RUNNER/SCRATCHES ON THE BODY
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AHHS1EKP00010595'

Lot 27 - 2002 HINO PROFIA 45-350 S/AXLE MECHANICAL HORSE



Colour: WHITE
Condition: NON RUNNER/SCRATCHES ON THE BODY
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AHHS1KFMXXX10020'

Lot 28 - 2003 HINO 16-237 65 SEATED BUS



Colour: WHITE
Condition: NON RUNNER/ RUST MARK AND SCRATCHES ALL OVER THE BODY
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AHGH1JR600011533'

Lot 29 - POOLE S/AXLE DROPSIDE SEMI TRAILER



Colour: WHITE
Condition: SCRATCHES ON THE BODY/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AAPV0471890649753'

Lot 30 - MOREWEAR S/AXLE DROPSIDE SEMI TRAILER



Condition: FAIR CONDITION
Qty: 1
Vin/serial No: 9797'
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO

Lot 31 - FORD RANGER 4X4 DOUBLE CAB



Colour: WHITE
Condition: NON RUNNER /SCRATCHES ON THE BODY/NO KEY/LOCKED
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 32 - 2001 TOYOTA HILUX 3.0D 4X4 SINGLE CAB



Colour: WHITE
Condition: NON RUNNER/RUST MARK AND SCRATCHES ALL OVER THE BODY/NO KEYS
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 33 - 2003 TOYOTA HILUX 2400D LWB SINGLE CAB



Colour: WHITE
Condition: NON RUNNER/RUST MARK AND SCRATCHES ALL OVER THE BODY/ NO KEYS/LOCKED/
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 34 - ISUZU 4X4 AMBULANCE (NEVER REGISTERED/ TO BE SOLD AS SPARES)



Colour: WHITE
Condition: NON RUNNER/ INTERIOR STRIPPED/ NO BATTERY/ RUST MARK AND SCRATCHES ALL OVER THE BODY/ DOOR HANDLE DAMAGED/
Qty: 1
No_of_keys: NO KEY
Vin/serial No: ADNTFS77H2B186963'

Lot 35 - 2002 TOYOTA HILUX 3.0DE 4X4 P/U S/C



Condition: NON RUNNER
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AHT31LNG908004529'
Reg_no: CXR881L

Lot 36 - 2008 FORD RANGER 2.5 TD 4X4 + P/U D/C



Condition: NON RUNNER
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AFATXXMJ2T8C03855'
Reg_no: BSB129L

Lot 37 - 2003 TOYOTA HILUX 2400D LWB P/U S/C



Condition: NON RUNNER
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: AHT31LNE508014629'
Reg_no: CXR898L

Lot 38 - VENTER BOX TRAILER (stripped)



Colour: WHITE
Condition: RUST MARK AND SCRATCHES ON THE BODY/DENT ON THE TOP FRONT PART/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: ABV1003SN2N6A0406'

Lot 39 - SELF MADE TRAILER (NEVER REGISTERED/ TO BE SOLD AS SPARES)



Colour: RED
Condition: RUST ON THE BODY/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NO TAG '

Lot 40 - LOT ASSORTED GEARBOXES & REAR AXLES




Qty: 1
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO

Lot 41 - ASSORTED CANOPIES FOR HILUX SINGLE CAB



Qty: 2
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO

Lot 42 - LOT ASSORTED BAKKIE SPARES



Qty: 1
LOCATION: DECLINE 1 - NORTHAM - LIMPOPO

Lot 50 - START OF SIBANYE STILLWATER ASSETS



Lot 51 - 2015 MERCEDES-BENZ SPRINTER 515 CDI F/C P/V



Colour: WHITE
Condition: RUNNER / REAR BADGE MISSING / BONNET DOES NOT OPEN /SOME FUZES MISSING
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 52 - UD PANORAMA 900S TRANSPORT BUS



Colour: WHITE
Condition: RUNNER / BACK
INSIDE BOARD BROKEN / RUST
MARKS VISIBLE / REAR BUMPER
DENTED /
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 53 - UD PANORAMA 900SLC TRANSPORT BUS



Colour: WHITE
Condition: RUNNER / RUST
MARKS VISIBLE / SOME SEATS
TORN
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 54 - UD PANORAMA 900S TRANSPORT BUS



Colour: WHITE
Condition: RUNNER / RUST
MARKS VISIBLE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 55 - 2016 TOYOTA HILUX 2.4 GD-6 SR 4X4 D/C



Colour: WHITE
Condition: NON RUNNER /
INJECTORS STRIPPED /
WINDSCREEN CRACKED/
WINDOWS BROKEN / TIRES FLAT /
BACK FLAP DENTED / RIM BENT
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 56 - 2011 TOYOTA HILUX 3.0 D-4D RAIDER D/C



Colour: WHITE
Condition: RUNNER / GEARBOX
FAULTY / CHASSIS CRACKED /
RUST MARKS VISIBLE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 57 - LOT ASSORTED CANOPIES



Qty: 1
LOCATION: KAREE WORKSHOP -
MARIKANA - NORTH WEST

Lot 58 - LOT ASSORTED ENGINE PARTS / SAFETY POSTERS



Qty: 1
LOCATION: KAREE WORKSHOP -
MARIKANA - NORTH WEST

Lot 59 - ASSORTED REAR MOUNTED CRANES



Qty: 8
LOCATION: KAREE WORKSHOP -
MARIKANA - NORTH WEST

Lot 70 - START OF TEICHMANN BOKSBURG ASSETS



Lot 71 - 2021 MITSUBISHI CANTER FUSO FE8-150 DROPSIDE



Colour: WHITE
Condition: GENERAL
APPEARANCE GOOD DROPSIDE
BODY HAS SCRATCHES AND
MARKS IN LINE WITH ANY
WORKING VEHICLE CAB EXTERIOR
IN VERY NICE CONDITION
WINDSCREEN NOT CRACKED CAB
INTERIOR IN GOOD CONDITION
CANVAS SEAT PROTECTORS
LIGHTS ALL WORKING DROPSIDE
FLAPS ALL WORKING CHEVRON
BOARD NO DAMAGE MUDFLAPS
PRESENT INNER AND OUTER
TYRES HAVE DIFFERENT TREAD
PATTERNS INNER TREAD ON
INNER TYRE IS PEELING OFF
Qty: 1
Mileage: 236420KM
Vin/serial No:
ABJFECX1HGEY00440'

Lot 72 - 2011 TOYOTA HILUX 2.5 D-4D SRX 4X4 P/U S/C



Colour: WHITE
Condition: GENERAL
APPEARANCE IS GOOD
MECHANICALLY SOUND ENGINE
RUNS AND SOUNDS GOOD
GEARBOX TAKES ALL GEARS
CLUTCH FEELS GOOD/ NOT
SPONGY OR GRATING GEARS
BRAKES GOOD BODYWORK IN
FAIR/GOOD CONDITION REAR BUN
IN GOOD CONDITION WITH
RUBBERISING IN PLACE
WINDSCREEN NO CRACKS LIGHTS
WORKING INTERIOR IN FAIR/GOOD
CONDITION CANVAS SEAT COVERS
RIGHT FRONT SPOTLIGHT COVER
MISSING BULLBAR AND TOWBAR
ATTACHED
Qty: 1
Mileage: 424681
Vin/serial No:
AHTDR22G905521284'

Lot 73 - START OF TEICHMANN DURBAN ASSETS



Lot 74 - BELL 754 TOW TRACTOR



Condition: GENERAL APPEARANCE VERY GOOD NO FLUID LEAKS CAB IN VERY GOOD CONDITION/ SMALL RUST SPOTSCAB GLASS IN GOOD CONDITIONAIR SYSTEM GOOD/ HOLDS PRESSURE ENGINE RUNS WELL/ NO STRANGE NOISES/TRANSMISSION CHANGES GEARS WELL STEERING GOODBRAKES GOOD

Qty: 1

LOCATION: DURBAN

Mileage: 2088 HOURS

Lot 80 - START OF PALESA HCI COAL ASSETS



Lot 81 - 2016 TOYOTA HILUX 2.4 GD-6 RB SRX P/U S/C



Colour: WHITE

Condition: RUNNER /SCRATCHES AND RUST MARKS NOTED ON THE BODY/1 X 12BATTERY/ LEFT DOOR SLIGHTLY DENTED/ 1 X RADIO/ NO SPARE WHEEL /4 STEEL RIMS

Qty: 1

Mileage: 307151

No_of_keys: 1

Lot 82 - 2019 TOYOTA HILUX 2.4 GD-6 RB SRX P/U S/C



Colour: WHITE

Condition: RUNNER/SCRATCHES AND RUST MARKS NOTED ON THE BODY/1 X 12BATTERY/ REAR BUMPER SLIGHTLYDAMAGED/ 1 X RADIO/ NO SPARE WHEEL/ 4 X MAG RIMS/PETROL TANK COVER SLIGHTLY DAMAGED

Qty: 1

Mileage: 307127

No_of_keys: 1

Lot 90 - START OF DEPARTMENT OF CORRECTIONAL SERVICES ASSETS



Lot 91 - 2011 FORDRANGER 3.0TDCi XLT 4X4 P/U SUP/CAB



Colour: CHARCOAL

Condition: NON-RUNNER/ ENGINE STRIPPED AND DISMANTLED/ GEARBOX VISIBLE/ PAINT FADING/ LEFT TAIL LIGHT DAMAGED/ SCRATCHES/ DENTS/ RUST VISIBLE

Qty: 1

Mileage: 246496 KM

No_of_keys: 1

Lot 92 - 2009 FORD FOCUS 2.0 Si A/T



Colour: WHITE

Condition: NON RUNNER/ ENGINE STRIPPED AND DISMANTLED/ SCRATCHES/ DENTS/ CHIPMARKS ON PAINT

Qty: 1

Mileage: 396482 KM

No_of_keys: 2

Lot 93 - 2011 FORD FOCUS 1.8 Si 5Dr



Colour: WHITE

Condition: NON-RUNNER/ ENGINE STRIPPED/ GEARBOX STRIPPED/ MINOR SCRATCHES AND DENTS

Qty: 1

Mileage: 289943 KM

No_of_keys: 1

Lot 100 - START OF SOUTH 32 ASSETS



Lot 101 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U C/C



Condition: NON-RUNNER/ ENGINE COMPLETE/ BATTERY INCLUDED/ SCRATCHES/ DENTS/ RUST VISIBLE/ DRIVER SEAT TORN/ GEAR LEVER STRIPPED/ ONE WHEEL FLAT

Qty: 1

Vin/serial No:

AFAPXXMJ2PFS89559'

Reg_no: CMF450NC

Engine_no: QJ2MPFS89559'

Lot 102 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U C/C



Condition: NON-RUNNER/ ENGINE STRIPPED/ NO BATTERY/ LEFT FENDER MISSING/ SCRATCHES/ DENTS/ LEFT REAR DOOR HANDLE MISSING/ REAR BADGE MISSING/ TOW BAR REMOVED/ RUST VISIBLE

Qty: 1

Vin/serial No:

AFAPXXMJ2PFS00484'

Reg_no: CMF447NC

Engine_no: QJ2MPFS00484'

Lot 103 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U D/C *SCRAPPED*



Colour: WHITE

Condition: NON-RUNNER COMPLETE/ DENTS/ SCRATCHES/ DRIVER WINDOW DAMAGED/ FRONT DRIVER AND PASSENGER SEATS TORN/ RUST VISIBLE/ ONE WHEEL FLAT/ BATTERY TERMINALS MISSING/ ONE DOOR HANDLE MISSING

Qty: 1

Mileage: NOT VISIBLE

No_of_keys: 1

Lot 104 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U D/C *SCRAPPED*



Colour: WHITE

Condition: NON-RUNNER COMPLETE/ DENTS/ SCRATCHES/ DRIVER SEAT TORN/ DASHBOARD SLIGHTLY STRIPPED/ FRONT DOOR PANELS SLIGHTLY STRIPPED/ CUBBY HOLE DISMANTLED/ LEFT FRONT DOOR HANDLE MISSING/ BOTH SIDE STEPS DENTED AND COVERS MISSING/ ONE BATTERY TERMINAL MISSING/ PIECE OF FRONT GRILL SLIGHTLY DAMAGED

Qty: 1

Mileage: NOT VISIBLE

No_of_keys: 1

Lot 105 - 2015 FORD RANGER 2.2TDCi XL PLUS 4X4 P/U D/C *SCRAPPED*



Colour: WHITE

Condition: NON-RUNNER COMPLETE/ DENTS/ SCRATCHES/ DRIVER SEAT TORN/ CUBBY HOLE DISMANTLED/ GEAR LEVER MISSING/LEFT FRONT DOOR PANEL SLIGHTLY STRIPPED/ FRONT BUMPER DAMAGED AND MISALIGNED/ LEFT REAR DOOR PANEL MISSING/ NO BATTERY/ FEW COVERS MISSING

Qty: 1

Mileage: NOT VISIBLE

No_of_keys: 1