


**October Mining Auction 2 :
Mining & Construction
Machinery and Allied Spares All
lots are sold STC**

Venue: **Northam & Polokwane, Limpopo**

Tuesday, 27 October @ 14h30


Lot 1 - SUBJECT TO CONFIRMATION PERIOD



Lot 5 - STRAT OF THARISA MINERALS




Lot 6 - 2000 LIEBHERR R9400 EXCAVATOR



Colour: WHITE
Condition: NON-RUNNER/ TRACKS ARE BROKEN/ MACHINE TRACKS HAVE BEEN DISMANTLED/ HYDRAULIC OIL LEAKS UNDERNEATH ENGINES/ MACHINE ENGINES SEEM COMPLETE/ SECONDARY ENGINE SEEMS STRIPPED/ MACHINE INTERIOR HAS BEEN STRIPPED AND IN POOR CONDITION

Qty: 1
Mileage: 48537
No_of_keys: 1

Lot 7 - 2000 LIEBHERR R9400 EXCAVATOR



Colour: WHITE
Condition: NON-RUNNER/ MACHINE BUCKET TEETH DAMAGED/ HYDRAULIC OIL LEAKS ON BOOM ON UNDERCARRIAGE/ MACHINE COULD NOT BE TESTED/ MACHINE TRACKS HAVE BEEN DAMAGED AND STRIPPED/ THERE SEEMS TO BE NO INDICATION OF DAMAGE ON THE ENGINE OF THE MACHINE/ MACHINE INTERIOR IS IN A FAIR CONDITION/ MACHINE IS IN A FAIR CONDITION

Qty: 1
Mileage: 52821
No_of_keys: 1

Lot 8 - 2008 LIEBHERR R9350 EXCAVATOR



Condition: TRACKS ARE DAMAGED/ ENGINE HAS BEEN STRIPPED/ STICK IS CRACKED/ HYDRAULIC OIL LEAKS ALL ROUND/ MACHINE INTERIOR HAS BEEN STRIPPED/ MACHINE IS IN A POOR CONDITION

Qty: 1
Vin/serial No: WLH20411JZG018542'
LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Lot 9 - 2008 LIEBHERR R9150 EXCAVATOR



Colour: WHITE
Condition: NON RUNNER/ NO BUCKET / NO TRACKS/ MACHINE HYDRAULIC PIPES HAVE BEEN STRIPPED/ ENGINE HAS BEEN STRIPPED MISSING ENGINE COVERS

Qty: 1
Mileage: 26514
No_of_keys: NOT VISIBLE

Lot 9A - 2008 LIEBHERR R9150 EXCAVATOR



Colour: WHITE
Condition: NON RUNNER/
MACHINE IS IN A POOR CONDITION
HYDRAULIC OIL LEAKS ON
MACHINE TURN TABLE/ ENGINE
COVERS ARE STRIPPED INTERIOR
IS STRIPPED
Qty: 1
Vin/serial No:
WLHZ1133CZE038006'
LOCATION: OLD ASSEMBLY YARD

Lot 10 - 2010 CAT 773F WATER BOWSER



Colour: Yellow
Condition: NON-RUNNER/ TYRES
ARE FLAT/ MACHINE IN A
RELATIVELY FAIR CONDITION/
Qty: 1
Mileage: 27268.2
No_of_keys: 1

Lot 11 - 2009 CAT 777D RIGID HAUL TRUCK



Colour: YELLOW
Condition: NON RUNNER/
HYDRAULIC OIL LEAKS ON THE
SHOCKS/ HYDRAULIC PIPES ARE
LOOSE/ BOTH REAR OUTER
WHEELS ARE MISSING/ REAR LEFT
WHEEL FLAT/ FAIR NO RADIO/
BATTERIES MISSING/ MACHINE IS
IN A FAIR CONDITION/ COULD NOT
BE TESTED
Qty: 1
Mileage: 55 000
Vin/serial No:
CAT0777DTFKR01506'

Lot 12 - 2011 CAT 777D RIGID HAUL TRUCK



Colour: YELLOW
Condition: NON RUNNER/
HYDRAULIC OIL LEAKS ALL
ROUND/ WHEELS ARE LEAKING
HYDRAULIC OIL/ REAR OUTER
WHEELS ARE MISSING/ ENGINE
SEEMS COMPLETE IN FAIR
CONDITION/ FAIR CONDITION
RADIO HAS BEEN STRIPPED
Qty: 1
Mileage: 55 000
Vin/serial No:
CAT0777DHFKR00805'

Lot 13 - 2008 CAT 777D RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/
MACHINE HAS NO ENGINE/ PART
OF CAB HAS BEEN STRIPPED/ NO
BUCKET/ NO TRANSMISSION/
INTERIOR IS IN A POOR
CONDITION
Qty: 1
Mileage: 53749.3
No_of_keys: 1

Lot 14 - 2011 CAT 777F RIGID HAUL TRUCK



Colour: YELLOW
Condition: NON-RUNNER/ NO
BUCKET/ MACHINE HAS BEEN
STRIPPED/ FRONT GRILL MISSING/
PART OF CAB & ENGINE COVER
MISSING/ BOTH REAR WHEELS
ARE MISSING/ ENGINE HAS BEEN
STRIPPED/ MACHINE HAS BEEN
FAIRLY STRIPPED
Qty: 1
Mileage: 41955
No_of_keys: 1

Lot 15 - 2011 CAT 777F RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/
MACHINE HAS NO BUCKET/
ENGINE SEEMS COMPLETE/
HYDRAULIC OIL LEAKS ALL
ROUND/ CAB HAS BEEN STRIPPED/
NO SEAT/ MACHINE HAS BEEN
LOCKED/
Qty: 1
Mileage: 47548.5
No_of_keys: 1

Lot 16 - 2011 CAT 777F RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/ NO
ENGINE/ NO WINDSCREEN/ NO
TRANSMISSION/ BUCKET HAS
BEEN RUSTED THROUGH/ WHEELS
ARE FLAT/ MACHINE IS IN POOR
CONDITION
Qty: 1
Mileage: 48377.4
No_of_keys: 1

Lot 17 - 2011 CAT 777F RIGID HAUL TRUCK



Colour: YELLOW
Condition: NON RUNNER/ BOTH REAR WHEELS ARE MISSING/ BUCKET IS MISSING/ ENGINE SEEMS COMPLETE COULD NOT TEST/ HYDRAULIC PIPES ARE LEAKING/ HYDRAULIC CYLINDERS FOR THE BUCKET ARE LOOSE/
Qty: 1
Mileage: 56360
No_of_keys: 1

Lot 18 - 2008 CAT 785C RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/ ENGINE HAS BEEN STRIPPED/ BOTH REAR WHEELS SEEM TO BE MISSING/ MACHINE BUCKET IS RUSTED THROUGH/ HYDRAULIC OIL LEAKS ALL ROUND/ INTERIOR HAS BEEN STRIPPED AND IS IN A POOR CONDITION/
Qty: 1
Mileage: 49001.4
No_of_keys: 1

Lot 19 - CAT 785C RIGID HAUL TRUCK (BARLOW REBUILT DATE:2021)



Colour: YELLOW
Condition: NON RUNNER/ HYDRAULIC OIL LEAKS/ REAR OUTER WHEELS MISSING/ ENGINE SEEMS COMPLETE AND MACHINE IS IN A FAIR CONDITION/ COULD NOT BE TESTED
Qty: 1
Mileage: 81643
Vin/serial No: APX01067'

Lot 20 - CAT 785C RIGID HAUL TRUCK (BARLOW REBUILT DATE: 2019)



Colour: YELLOW
Condition: NON RUNNER/ BOTH REAR WHEELS HAVE BEEN REMOVED/ HYDRAULIC OIL LEAKS/ DASHBOARD HAS BEEN STRIPPED/ MACHINE HAS ALL COMPONENTS INTACT
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: 1

Lot 21 - 2011 CAT 785D RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/ MACHINE HAS BEEN STRIPPED/ NO GRILL/ NO RADIATOR/ DIESEL TANK HAS BEEN STRIPPED/ NO BUCKET/ ONLY TWO REAR WHEELS/ MAJOR COMPONENTS HAVE BEEN STRIPPED FROM ENGINE/ INTERIOR HAS BEEN STRIPPED
Qty: 1
Mileage: 51386.3
No_of_keys: 1

Lot 22 - 2011 CAT 789C RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/ MACHINE HAS NO BUCKET/ ENGINE HAS BEEN STRIPPED/ NO TRANSMISSION/ NO CAB/ NO REAR WHEELS/ MACHINE IS IN A POOR CONDITION
Qty: 1
Mileage: 70000
No_of_keys: 1

Lot 23 - 2011 CAT 789C RIGID HAUL TRUCK



Colour: Yellow
Condition: NON-RUNNER/ ENGINE HAS BEEN STRIPPED/ NO BUCKET/ LOOSE SPARES UNDERNEATH THE MACHINE/ FRONT WHEELS ARE FLAT/ MACHINE IS IN A FAIR CONDITION
Qty: 1
Mileage: 49807.8
No_of_keys: 1

Lot 24 - 2022 CAT 745C ADT



Colour: Yellow
Condition: NON-RUNNER/ BONNET DAMAGED/ LIGHTS DAMAGED/ MACHINE SEEMS TO HAVE TIPPED OVER/ HYDRAULIC OIL LEAKS FROM WHEELS/ WHEELS ARE FLAT/ REAR RIGHT WHEEL MISSING/ LEFT MIDDLE WHEEL MISSING/ CAB HAS BEEN DAMAGED/ CENTRE COMPLETE AXLE
Qty: 1
Mileage: 19140
No_of_keys: 1

Lot 25 - 2019 CAT 745C ADT



Colour: Yellow
Condition: NON-RUNNER/ ENGINE SEEMS COMPLETE/ NO BUCKET/ MACHINE IN FAIR CONDITION
Qty: 1
Mileage: 18699.4
No_of_keys: 1

Lot 26 - 2020 CAT 745C ADT



Colour: Yellow
Condition: NON-RUNNER/ NO BUCKET/ MACHINE SEEMS IN A FAIR CONDITION
Qty: 1
Mileage: 23718.7
No_of_keys: 1

Lot 27 - CAT 745C ADT



Colour: YELLOW
Condition: POSSIBLE RUNNER/ MACHINE WAS DRIVEN TO THE ASSEMBLY YARD/ MACHINE HAS NO BUCKET/ MACHINE IS IN AN OVERALL FAIR CONDITION
Qty: 1
Mileage: 24033
No_of_keys: NO KEYS

Lot 28 - 2017 CAT D10T TRACK DOZER



Colour: YELLOW
Condition: NON RUNNER/ NO TRACKS/ NO ENGINE/ NO DOZER BLADE/ INTERIOR IN A POOR CONDITION/ MACHINE IN A VERY POOR CONDITION
Qty: 1
Mileage: 33 176
Vin/serial No: EHX07588'

Lot 29 - CAT D9T TRACK DOZER



Condition: NON RUNNER / RUSTED / HYDRAULIC LIFT CYLINDERS MISSING / INTERIOR STRIPPED
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST
Mileage: 29 729
Vin/serial No: CAT00D9TVTWG00580'
Engine_no: C18'

Lot 30 - 2000 CAT D9T DOZER



Colour: Yellow
Condition: NON-RUNNER/ ENGINE SEEMS COMPLETE/ TRACKS ARE IN FAIR CONDITION/ MACHINE IS IN AN OVERALL FAIR CONDITION
Qty: 1
Mileage: 28396.7
No_of_keys: 1

Lot 31 - 2007 CAT D10T DOZER



Colour: Yellow
Condition: NON-RUNNER/ NO BLADE/ NO TRACKS/ MACHINE HAS BEEN COMPLETELY STRIPPED
Qty: 1
Mileage: 29161.1
No_of_keys: 1

Lot 32 - 2007 CAT D10T DOZER



Colour: Yellow
Condition: NON RUNNER/ MACHINE IS IN A FAIR CONDITION
Qty: 1
Mileage: 32796.3
No_of_keys: 1

Lot 32A - CAT D10T DOZER



Condition: NON RUNNER / DRIVE TRAIN REMOVED/ TORQUE CONVERTER/ TRANSMISSION AND 2 FINAL DRIVES / ENGINE TURBO PIPES REMOVED/ LEFT OPEN TO THE ELEMENTS / ENGINE TAPPET COVERS REMOVED/ LEFT OPEN TO THE ELEMENTS / COOLING PIPES REMOVED / BLADE PUSHARMS WITH TRUNIONS HAVE BEEN REMOVED/ / TORQUE CONVERTER REMOVED / VALVE BANK REMOVED / PUMPS REMOVED
Qty: 1
LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST
Mileage: NOT VISIBLE

Lot 33 - 2000 CAT 834H WHEEL DOZER



Colour: Yellow
Condition: NON-RUNNER/ MACHINE IS IN A FAIR CONDITION/ ENGINE SEEMS COMPLETE/ COVERS ARE DAMAGED/ INTERIOR HAS BEEN STRIPPED/ COVERS ARE STRIPPED
Qty: 1
Mileage: 27283.7
No_of_keys: 1

Lot 34 - 2010 CAT 980G TYRE HANDLER



Colour: Yellow
Condition: NON-RUNNER/ HYDRAULIC OIL LEAKS ON THE CYLINDERS/ INTERIOR HAS BEEN STRIPPED/ ENGINE SEEMS COMPLETE COULD NOT TEST MACHINE/ MACHINE HAS NO SERIAL TAG
Qty: 1
Mileage: 26862
No_of_keys: 1

Lot 35 - 2008 CAT 16M GRADER



Colour: Yellow
Condition: NON-RUNNER/ FRONT RIGHT WHEEL MISSING/ ALL WHEELS ARE FLAT/ NO TURN TABLE/ NO SCRAPER/ ENGINE HAS BEEN STRIPPED
Qty: 1
Mileage: 24744.4
No_of_keys: 1

Lot 36 - 2017 CAT 16M GRADER



Colour: Yellow
Condition: NON-RUNNER/ HYDRAULIC OIL LEAKS ON WHEELS/ ENGINE SEEMS COMPLETE AND MACHINE IN A FAIR CONDITION
Qty: 1
Mileage: 26925
No_of_keys: 1

Lot 37 - 2017 CAT 374FL EXCAVATOR



Colour: YELLOW
Condition: NON-RUNNER/ MACHINE IS IN A FAIR CONDITION/ MACHINE COULD NOT BE TESTED/ MACHINE TRACKS SEEM FAIR/ BUCKET IS IN A FAIR CONDITION/ NO MAJOR COMPONENTS HAVE BEEN REMOVED FROM THE MACHINE
Qty: 1
Mileage: 22614.1
No_of_keys: 1

Lot 38 - 2000 LIEBHERR R974C EXCAVATOR



Colour: YELLOW/WHITE
Condition: NON-RUNNER/ MACHINE HAS BEEN STRIPPED/ COMPONENTS HAVE BEEN REMOVED FROM THE ENGINE/ ELECTRICAL COMPONENTS HAVE BEEN REMOVED FROM THE INTERIOR/ TRACKS ARE CRACKED AND BROKEN/ OIL TANK HAS BEEN DAMAGED/ MACHINE IN A POOR CONDITION
Qty: 1
Mileage: 26238
No_of_keys: 1

Lot 39 - 2010 LIEBHERR R964C EXCAVATOR



Colour: Yellow/White
Condition: NON-RUNNER/ TRACKS ARE STRIPPED/ MACHINE ENGINE COVERS RUSTED THROUGH/ HYDRAULIC PIPES ARE LOOSE ON BOOM/ MACHINE ENGINE HAS BEEN STRIPPED
Qty: 1
Mileage: 23996.4
No_of_keys: 1

Lot 40 - 2000 LIEBHERR R964C EXCAVATOR




Colour: Yellow/White
Condition: NON-RUNNER/ TRACKS ARE DAMAGED/ BOOM HAS HYDRAULIC OIL LEAKS ALL ROUND/ ENGINE HAS BEEN STRIPPED/ MACHINE IS IN A POOR CONDITION
Qty: 1
Mileage: 22408
No_of_keys: 1

Lot 41 - 2014 LIEBHERR R970C EXCAVATOR



Colour: Yellow/White
Condition: NON-RUNNER/ NO MACHINE BUCKET/ MACHINE ENGINE HAS BEEN STRIPPED/ MACHINE HAS MISSING COMPONENTS/ CYLINDERS ARE DAMAGED/ HYDRAULIC OIL LEAKS ALL ROUND
Qty: 1
Mileage: 24000
No_of_keys: 1

Lot 42 - 2008 LIEBHERR R984C EXCAVATOR



Colour: White
Condition: NON-RUNNER/ MACHINE SEEMS COMPLETE/ MACHINE HAS NOT BEEN STRIPPED/ TRACKS ARE COMPLETE/ MACHINE CAB IS LOCKED
Qty: 1
Mileage: 36296
No_of_keys: 1

Lot 43 - 2012 LIEBHERR R984C HD EXCAVATOR



Condition: NON RUNNER/ MACHINE TRACKS ARE STRIPPED/ MACHINE BUCKET MISSING/ MACHINE ENGINE COMPONENTS HAVE BEEN REMOVED
Qty: 1
Vin/serial No: WLHZ0922TZE035028'
LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Lot 44 - 2011 LIEBHERR R974C LITRONIC EXCAVATOR



Colour: YELLOW
Condition: NON RUNNER/ NO BOOM/ NO STICK/ NO BUCKET/ TRACKS SEEM DAMAGED/ POOR CONDITION MACHINE INTERIOR ALSO POOR AND STRIPPED
Qty: 1
Mileage: NOT VISIBLE
Vin/serial No: WLHZ1011JZC032213'

Lot 45 - 2019 SUPER ROCK DRILL SRD5000 DRILL RIG




Colour: Blue
Condition: NON-RUNNER/ MACHINE IS FAIRLY COMPLETE
Qty: 1
Mileage: 7432
No_of_keys: 1

Lot 46 - 2019 SUPER ROCK DRILL SRD5000 DRILL RIG



Colour: Blue
Condition: NON-RUNNER/ MACHINE IS FAIRLY COMPLETE
Qty: 1
Mileage: 10068
No_of_keys: 1

Lot 47 - 2017 ATLAS COPCO T45 DRILL RIG



Colour: Yellow
Condition: NON-RUNNER
Qty: 1
Mileage: 31675
No_of_keys: 1

Lot 48 - 2017 CAT 428F2 TLB



Colour: Yellow
Condition: NON-RUNNER/ REAR LEFT WHEEL MISSING/ ENGINE HAS BEEN STRIPPED/ MACHINE IS IN A FAIR CONDITION
Qty: 1
Mileage: 6245.2
No_of_keys: 1

Lot 49 - 2017 CAT 428F2 TLB



Colour: Yellow
Condition: NON-RUNNER/ LEFT FRONT WHEEL MISSING/ SEATS IN BUCKET/ ENGINE HAS BEEN STRIPPED/ NO BATTERIES/ INTERIOR HAS BEEN STRIPPED/
Qty: 1
Mileage: 3012.4
No_of_keys: 1

Lot 50 - 2017 CAT TH514C TELEHANDLER



Colour: YELLOW
Condition: NON RUNNER/ TWO WHEELS DISMANTLED/ PROPSHAFT DISMANTLED/ INTERIOR IS FAIR/ NO BUCKET/ ENGINE SEEMS COMPLETE/ COULD NOT BE TESTED
Qty: 1
Mileage: 5 426
Vin/serial No: KKW00311'

Lot 51 - 2018 CAT TH514C TELEHANDLER



Colour: Yellow
Condition: NON-RUNNER/ SPARES AROUND MACHINE INCLUDED/ MACHINE HAS LOOSE AND STRIPPED PIPES IN ENGINE/ MACHINE HAS NO BUCKET/ RIGHT FRONT WHEEL MISSING/ INTERIOR POOR/ DOOR WINDOW BROKEN
Qty: 1
Mileage: 6996
No_of_keys: 1

Lot 52 - EXCAVATOR FRAME (NO ENGINE)



Qty: 1
LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Lot 53 - CAT D10T TRANSMISSION & CAT C15 ENGINE



Condition: TRANSMISSION & ENGINE ARE OPEN
Qty: 1
Vin/serial No: 0002307 & TXY03555'
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 54 - CAT 777D ENGINE COMPLETE



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 55 - CAT C11 ENGINE



Vin/serial No: HRA04162'
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 56 - CAT C11 ENGINE



LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 57 - CAT 3512B ENGINE



Qty: 1
Vin/serial No: 2100263138'
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 58 - CAT C11 ENGINE



Qty: 1
Vin/serial No: HRA04324'
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 59 - CAT C11 ENGINE



Qty: 1
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 60 - CAT C11 ENGINE



Qty: 1
Vin/serial No: KHRA04295'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 61 - CAT C11 ENGINE (STRIPPED HOLE IN BLOCK)



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 62 - CAT C11 ENGINE



Qty: 1
Vin/serial No: MCW16182'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 63 - CAT C27 ENGINE



Condition: ENGINE IS
COMPLETELY STRIPPED
Qty: 1
Vin/serial No: EHX06185'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 64 - CAT C15 ENGINE



Qty: 1
Vin/serial No: MCW1043W'
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 65 - CAT C15 ENGINE




Qty: 1
Vin/serial No: MCW15675'
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 66 - CAT 3512 ENGINE




Qty: 1
Vin/serial No: EEE00203'
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 67 - CAT 3512 ENGINE



Qty: 1
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 68 - CAT 3512 ENGINE



Qty: 1
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 69 - CAT 3512 ENGINE



Qty: 1
Vin/serial No: 88R01645'
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 70 - CAT 3512 ENGINE FOR 785 DUMP TRUCK



Qty: 1
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 71 - CAT ENGINE STANDS



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 72 - CAT TRANSMISSION



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 73 - CAT TRANSMISSION



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 74 - ATLAS COPCO TRANSMISSION



Qty: 1
Vin/serial No: 816100990E'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 75 - ATLAS COPCO TRANSMISSION



Qty: 1
Vin/serial No: 8161000776'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 76 - ATLAS COPCO TRANSMISSION



Qty: 1
Vin/serial No: 8161000776'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 77 - 2020 CAT 785C TRANSMISSION



Qty: 1
Vin/serial No: 6Y5645'
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 78 - CAT 785 & 777 TRANSMISSIONS (WITH SPARES FOR CAT MACHINES)



Qty: 2
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 79 - LOT ASSORTED CAT SPARES/ TRANSMISSIONS/ FRAMES/ PUMPS



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 80 - LOT CAT DOZER SPARES/ RADIATOR/ FINAL DRIVES WITH SPARES



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 81 - LOT ASSORTED CAT SPARES



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 82 - LOT ASSORTED CAT SPARES/ CYLINDERS/ STEPS/ LADDERS/ FILTERS & COUNTER WEIGHT



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 83 - SERVICE TRUCK SPARE



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 84 - LOT ASSORTED CAT SPARES INCL. TRANSMISSION SPARES/ ROLLERS/ DIESEL TANK/ CYLINDERS



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 85 - LOT ASSORTED DOZER SPARES/ TRACK FRAMES/ TYRE/ CYLINDERS



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 86 - ASSORTED TRACKS (ITR C31 LH)



Qty: 2
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 87 - ASSORTED TRACKS (ITR C31 LH)



Qty: 2
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 88 - LOT TRACKS (037 ITR RH)



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 89 - DOZER TRACK FRAMES



Qty: 2
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 90 - DOZER TRACK FRAMES



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 91 - EPIROC TRACK FRAMES & 1 STRIPPED DRIFTER



Qty: 1
LOCATION: SALVAGE YARD -
MARIKANA - NORTH WEST

Lot 92 - CAT FINAL DRIVE FOR 777D DUMP TRUCK



Qty: 1
LOCATION: OLD ASSEMBLY YARD -
MARIKANA - NORTH WEST

Lot 93 - CAT FINAL DRIVE FOR 789 DUMP TRUCK



Qty: 1
LOCATION: OLD ASSEMBLY YARD -
MARIKANA - NORTH WEST

Lot 94 - CAT FINAL DRIVE FOR 789 DUMP TRUCK



Qty: 1
LOCATION: OLD ASSEMBLY YARD -
MARIKANA - NORTH WEST

Lot 95 - LIEBHERR R 9200 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD -
MARIKANA - NORTH WEST

Lot 96 - LIEBHERR R 974 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 97 - LIEBHERR R 984 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 98 - LIEBHERR R 9400 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 99 - LIEBHERR R 9350 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 100 - LIEBHERR R 9150 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 101 - LIEBHERR R 9150 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 102 - LIEBHERR R 984 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 103 - LIEBHERR R 9150 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 104 - LIEBHERR R 9150 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 105 - LIEBHERR R 9350 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 106 - LIEBHERR R 964 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 107 - LIEBHERR R 9150 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 108 - LIEBHERR R 984 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 109 - LIEBHERR R 984 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 110 - LIEBHERR R 9350 MINING EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 111 - LIEBHERR R 974 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 112 - LIEBHERR R 984 EXCAVATOR BUCKET



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 113 - DUMP TRUCK BIN



Qty: 1
LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 114 - LIEBHERR R 964 EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 115 - LIEBHERR R 964 EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 116 - LIEBHERR R 974 EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 117 - LIEBHERR R 974 EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 118 - LIEBHERR R 974 LITRONIC CRAWLER EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 119 - UPPER FOOT/BASE SECTION OF THE LIEBHERR 974 EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 120 - LIEBHERR R 984 EXCAVATOR BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 121 - LIEBHERR 974 STICK



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 122 - LIEBHERR R 964 EXCAVATOR STICK



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 123 - LIEBHERR R 964 EXCAVATOR STICK



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 124 - LIEBHERR R 984 CRAWLER EXCAVATOR STICK



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 125 - LIEBHERR R 984 EXCAVATOR STICK



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 126 - LIEBHERR 984 BOOM ATTACHMENT



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 127 - LIEBHERR 974 HYDRAULIC EXCAVATOR MONO BOOM



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 128 - LOT ASSORTED HYDRAULIC CYLINDERS



LOCATION: OLD ASSEMBLY YARD
- MARIKANA - NORTH WEST

Lot 129 - ESCO SUPER V V69SD SERIES BUCKET TOOTH TIPS



Qty: 9

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 130 - ESCO V71SD MINING TOOTH TIPS



Qty: 15

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 131 - ESCO PAT 5709043 SV2 HAMMERLESS TOOTH TIPS



Qty: 3

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 132 - MTG STARMET TOOTH TIPS



Qty: 5

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 133 - CAT CORNER ADAPTERS



Qty: 8

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 134 - CAT BUCKET LIP SHROUD



Qty: 5

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 135 - (CAT) EXTREME DUTY COUPLERS / ADAPTERS



Qty: 8

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 136 - CRAWLER CRANE OR DRILL RIG UNDERCARRIAGE TRACK FRAME COMPONENTS



Qty: 4

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 137 - EXCAVATOR QUICK COUPLERS



Qty: 2

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 138 - HEAVY-DUTY ATTACHMENT MOUNTING PINS



Qty: 2

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 139 - MINING DRILL RIG INSTALLATION HARDWARE AND STRUCTURAL MOUNTS



Qty: 2

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 140 - EPIROC RIGHT-SIDE TRACK FRAME



Qty: 1

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 144 - CAT HEAVY-DUTY EXCAVATOR BUCKET



Qty: 1

LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 145 - HYDRAULIC CYLINDERS FOR D55 AND EPIROC T45



Qty: 8
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 146 - BOOM LIFT CYLINDERS FOR EPIROC T45
ABD EPIROC D65**



Qty: 9
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 147 - LOT ASSORTED HYD CYLINDERS AND
BREAKOUT CYLINDERS FOR EPIROC T45**



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 148 - HYDRAULIC PUMPS FOR EPIROC T45



Qty: 2
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 149 - PROTECTION ARCH FOR EPIROC T45



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 150 - TRACK PROTECTION LINERS/HOOD AND
PROTECTION ARCH FOR EPIROC T45**



Qty: 2
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 151 - DRIVE UNIT AND GEAR BOX FOR EPIROC
T45**



Qty: 2
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 152 - LOT ASSORTED EPIROC T45 AND EPIROC
D65 SPARES**



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 153 - LOT ASSORTED EPIROC T45 AND EPIROC
D65 SPARES**



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

**Lot 154 - LOT ASSORTED EPIROC T45 AND EPIROC
D65 SPARES**



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 155 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 156 - COMPLETE OVERHAUL KIT FOR EPIROC T45 AND SPARES



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 157 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 158 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 159 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 160 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 161 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 162 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 163 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



Qty: 1
LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 164 - LOT ASSORTED EPIROC T45 AND EPIROC D65 SPARES



LOCATION: MINING STORES -
MARIKANA - NORTH WEST

Lot 180 - START OF SIYANDA BAKGATLA ASSETS



Lot 181 - TCM FD70 FORKLIFT(7TON)



Colour: WHITE
Condition: NON RUNNER/ RUST
MARK AND SCRATCHES ALL OVER
THE BODY/
Qty: 1
Mileage: 6513
No_of_keys: NO KEYS

Lot 182 - MAXUM B PERSONAL CARRIER



Colour: WHITE
Condition: NON RUNNER/SCRATCHES ALL OVER THE BODY/ INTERIOR STRIPPED/PRIME PUMP STRIPPED /DIESEL PIPES LOOSE/NO KEY
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NO TAG '

Lot 183 - MAXUM B PERSONAL CARRIER



Colour: WHITE
Condition: NON RUNNER/RUST MARK AND SCRATCHES ALL OVER THE BODY/ REAR AXCEL MISSING/INTERIOR STRIPPED/ NO KEYS
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NO TAG '

Lot 184 - FERMEL SCALER



Colour: YELLOW
Condition: NON RUNNER/ NO BATTERY/ STARTER MISSING/RUST MARK AND SCRATCHES ALL OVER THE BODY/ FRONT RIGHT HUB MISSING/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NO TAG '

Lot 185 - GST DRILL RIG



Colour: YELLOW
Condition: NON RUNNER/RUST MARK AND SCRATCHES ALL OVER THE BODY/ NO BATTERY/ HYDRAULIC PIPES LOOSE/ ENGINE COVER LOOSE/INTERIOR STRIPPED/
Mileage: 768
No_of_keys: NO KEY
Vin/serial No: NO TAG '

Lot 186 - FERMEL LOW PROFILE GRADER



Colour: YELLOW
Condition: NON RUNNER/RUST MARK AND SCRATCHES ALL OVER THE BODY/ INTERIOR STRIPPED/ TRANSMISSION MISSING/HYDRAULIC PIPES DISCONNECT/ NO BATTERY/ ENGINE COVER MISSING
No_of_keys: NO KEY
Vin/serial No: NO TAG '
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 187 - FERMEL UTILITY VEHICLE



Colour: YELLOW
Condition: NON RUNNER/NO ENGINE/ NO TRANSMISSION/ HYDRAULIC PIPES LOOSE /RUST MARK AND SCRATCHES ALL OVER THE BODY/
No_of_keys: NO KEY
Vin/serial No: NO TAG '
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 188 - FERMEL SCALER



Colour: YELLOW
Condition: NON RUNNER/NO BATTERY/ HYDRAULIC PIPES DISMANTLED/RUST MARK AND SCRATCHES ALL OVER THE BODY/
No_of_keys: NO KEY
Vin/serial No: 7299'
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 189 - FERMEL UTILITY VEHICLE



Colour: YELLOW
Condition: NON RUNNER/ NO BATTERY/ HYDRAULIC PIPES DISMANTLED/ NO ENGINE/ NO TRANSMISSION/ INTERIOR STRIPPED/ RUST MARK AND SCRATCHES ALL OVER THE BODY/
No_of_keys: NO KEY
Vin/serial No: NO TAG '
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 190 - FERMEL UTILITY VEHICLE



Colour: YELLOW
Condition: NON RUNNER/NO BATTERY/ RUST MARK AND SCRATCHES ALL OVER THE BODY/ INTERIOR STRIPPED/
No_of_keys: NO KEY
Vin/serial No: NO TAG '
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 191 - FERMEL UTILITY VEHICLE



Colour: YELLOW
Condition: NON RUNNER /NO BATTERY/ NO TRANSMISSION/ RUST MARK AND SCRATCHES ALL OVER THE BODY/ INTERIOR STRIPPED/
No_of_keys: NO KEY
Vin/serial No: NO TAG '
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 192 - 2010 FERMEL UTILITY VEHICLE (CASSETTE LOADER)



Colour: YELLOW
Condition: FAIR CONDITION/ NO BATTERY/ CLUSTER LOOSE/ NO DRIVER'S SEAT/ HYDRAULIC PIPES LOOSE/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: 5092'

Lot 193 - 2010 FERMEL UTILITY VEHICLE (CASSETTE LOADER)



Colour: YELLOW
Condition: POOR CONDITION/ INTERIOR STRIPPED/ ENGINE COVERS MISSING/ NO BATTERY/ COMPONENTS STRIPPED/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NO TAG'

Lot 194 - FERMEL UNDERGROUND JEEP BODY



Colour: YELLOW
Condition: POOR CONDITION/ NO ENGINE/ NO GEARBOX/ NO BATTERY/ ALL WHEELS MISSING/ INTERIOR STRIPPED/
Qty: 1
No_of_keys: NO KEY
Vin/serial No: NO TAG'

Lot 195 - FERMEL UNDERGROUND JEEP



Colour: YELLOW
Condition: POOR CONDITION/ NO BATTERY/ ALL WHEELS MISSING
Qty: 1
No_of_keys: NO KEY
Vin/serial No: NO TAG'

Lot 196 - FERMEL UTILITY VEHICLE (CASSETTE LOADER)



Colour: YELLOW
Condition: POOR CONDITION/ DISMANTLED/ NO BATTERY/ NO ENGINE/ NO GEARBOX HYDRAULIC PUMP MISSING/
Qty: 1
No_of_keys: NO KEY
Vin/serial No: 6956'

Lot 197 - GST DILL RIG



Colour: YELLOW
Condition: NON RUNNER/ OIL LEAKS/ SCRATCHES ALL OVER THE BODY/ NO SEAT/ NO BATTERY
Qty: 1
Mileage: 765
No_of_keys: NO KEY

Lot 198 - GST DILL RIG



Colour: YELLOW
Condition: NON RUNNER/ NO BATTERY/ BACK GRILL MISSING/ DRILLING ATTACHMENT MISSING/ NO SEAT/ SCRATCHES ALL OVER THE BODY
Qty: 1
Mileage: 899
No_of_keys: NO KEY

Lot 199 - UNDERGROUND DRILL RIG



Qty: 1
LOCATION: NORTHAM - LIMPOPO

Lot 200 - LHD FRAME



Qty: 1
LOCATION: NORTHAM - LIMPOPO

Lot 201 - CASSETTE FUEL TANK



Qty: 1
LOCATION: NORTHAM - LIMPOPO

Lot 202 - FERMEL TYRE HANDLER ATTACHMENT



Qty: 1
LOCATION: NORTHAM - LIMPOPO

Lot 205 - LOT ASSORTED HEAVY DUTY TYRES



Qty: 1
LOCATION: SALVAGE YARD - NORTHAM - LIMPOPO

Lot 206 - UNDERGROUND LOADER FRAME



Qty: 1
LOCATION: SPUD SHAFT -
NORTHAM - LIMPOPO

Lot 220 - START OF SIBANYE STILLWATER ASSETS



Lot 221 - AARD 5.5 LHD



Colour: WHITE
Condition: NON RUNNER/ ENGINE
SEEMS COMPLETE/ CYLINDERS AT
ARTICULATION IS LOOSE/
CONTROLS ARE STRIPPED AND
DAMAGED/ TIRES ARE WORN/
HYDRAULIC OIL LEAKS IN FRONT
WHEELS/
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: NO KEYS

Lot 230 - FRANNA 4WD-MAC14 MOBILIFT



Colour: WHITE
Condition: RUNNER / RUST
MARKS VISIBLE / SEAT TORN / ONE
TIRE SLASHED / WINDSHIELD
CRACKED
Qty: 1
Mileage: 8051 HOURS
No_of_keys: NO KEYS

Lot 231 - FRANNA 4WD-MAC14 MOBILIFT



Colour: WHITE
Condition: NON RUNNER /
GEARBOX FAULTY / ENGINE
STARTS / RUST MARKS VISIBLE/
WINDSCREEN CRACKED / ENGINE
COVER LOOSE / HYDRAULIC OIL
LEAKS ON ARTICULATION
Qty: 1
Mileage: 5151 HOURS
No_of_keys: NO KEYS

Lot 232 - 2007 MANITOU M30-2 FORKLIFT



Colour: RED
Condition: RUNNER / FRONT
COVER MISSING / RUST MARKS
VISIBLE
Qty: 1
Mileage: 2745 HOURS
Vin/serial No: 246717'

Lot 233 - ASSORTED MUCKING MACHINE BUCKETS



Qty: 4
LOCATION: KUSELEKA SHAFT -
RUSTENBURG - NORTH WEST

Lot 234 - ASSORTED MUCKING MACHINE BUCKETS



Qty: 4
LOCATION: KUSELEKA SHAFT -
RUSTENBURG - NORTH WEST

Lot 235 - ASSORTED MUCKING MACHINE BUCKETS



Qty: 3
LOCATION: KUSELEKA SHAFT -
RUSTENBURG - NORTH WEST

Lot 236 - SALZGITTER MZANSI MUCKING MACHINE



Condition: STRIPPED AND
RUSTED MISSING SPARES/ WITH
WHEEL NEXT TO IT
Qty: 1
Vin/serial No: CDS14'
LOCATION: KUSELEKA SHAFT -
RUSTENBURG - NORTH WEST

Lot 237 - TRIDENT SA MUCKING MACHINE



Condition: STRIPPED AND
RUSTED/ MISSING PARTS/
HYDRAULIC OIL LEAKAGE
Qty: 1
Vin/serial No: UG2WEST16'
LOCATION: KUSELEKA SHAFT -
RUSTENBURG - NORTH WEST

Lot 238 - SALZGITTER MZANSI MUCKING MACHINE



Condition: STRIPPED AND
RUSTED MISSING SPARES/
HYDRAULIC LEAKAGE ALL ROUND
Qty: 1
Vin/serial No: CDS09'
LOCATION: KUSELEKA SHAFT -
RUSTENBURG - NORTH WEST

Lot 239 - SALZGITTER MZANSI MUCKING MACHINE



Condition: STRIPPED AND RUSTED/ INCLUDING GEAR IN FRONT OF BOESMAN
Qty: 1
Vin/serial No: CDS015'
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 240 - SALZGITTER MZANSI MUCKING MACHINE



Condition: STRIPPED AND RUSTED/ INCLUDING SPARES AROUND IT/ HYDRAULIC LEAKAGE
Qty: 1
Vin/serial No: CDS08'
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 241 - EIMCO MUCKING MACHINE WITH BUCKET ATTACHMENT



Condition: BOESMAN SEEMS COMPLETE/ PIPES ARE STRIPPED/ MACHINE IS RUSTED
Qty: 1
Vin/serial No: 2260'
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 242 - SALZGITTER MZANSI MUCKING MACHINE WITH BUCKET ATTACHMENT



Condition: BOESMAN SEEMS COMPLETE & RUSTED
Qty: 1
Vin/serial No: CDS16'
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 243 - SALZGITTER MZANSI MUCKING MACHINE



Condition: STRIPPED/ CHAIN IS LOOSE/ RUSTED
Qty: 1
Vin/serial No: CDS05'
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 244 - SALZGITTER MZANSI MUCKING MACHINE



Condition: STRIPPED/ CHAIN BROKEN/ RUSTED
Qty: 1
Vin/serial No: CDS20'
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 245 - EIMCO MUCKING MACHINE WITH BUCKET



Condition: FAIR CONDITION
Qty: 1
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 246 - EIMCO MUCKING MACHINE



Condition: STRIPPED AND NO BUCKET
Qty: 1
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 247 - LOT ASSORTED PIPES & FITTINGS/ MUCKING MACHINE GEAR/ MUCKING MACHINE SPARES/ SCAFFOLDING/ EXLUDING THE BUFFER



Qty: 1
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 248 - TRIDENT LOADER SILENCER



Qty: 10
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 249 - SALZGITTER MZANSI MUCKING MACHINE



Qty: 1
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 260 - START OF TEICHMANN BOKSBURG ASSETS



Lot 261 - 2011 ASPHALT CIBER PLANT UACF 17P-2 ADVANCED



Condition: WORKING CONDITION
Qty: 1
LOCATION: BOKSBURG
Mileage: 928 HOURS

Lot 262 - 2011 BOMAG BW151AD-4 8 TON



Condition: NO MAJOR FAULTS RECORDED THIS MACHINE IS IN A VERY GOOD CONDITION NO OIL OR COOLANT LEAKS VISIBLE ASPHALT CUTTER / TRIMMER IS WORKING WELL AMPLITUDE FREQUENCY IS WORKING (HIGH AND LOW)
Qty: 1
LOCATION: BOKSBURG
Mileage: 1681 HOURS
Vin/serial No: BW151AD'

Lot 263 - 2017 CAT 320D EXCAVATOR



Condition: MACHINE IS PIPED FOR HAMMER USE/ MACHINE IS IN FAIR ALL-ROUND CONDITION/ REPAIR CYLINDER LEAKS AND THE MACHINE CAN GO TO SITE HAS WINDSCREEN BARS FOR FLYING STONE PROTECTION WHEN USING HAMMER/
Qty: 1
LOCATION: BOKSBURG
Mileage: 15292 HOURS
Vin/serial No: CAT320DCDNS10051'

Lot 264 - 1997 LIEBHERR LTM 70 TON 1070/1 MOBILE CRANE



Condition: RUNNER/COMPANY CARRIES OUT STRICT SERVICE INTERVALS BENT BOOM SECTION AND COMPUTER PROBLEM
Qty: 1
Vin/serial No: 23418'
LOCATION: BOKSBURG

Lot 265 - 2001 WINGET HT DUMPER



Condition: RUNNING/ VERY NEAT LITTLE DUMPER/ BEEN THROUGH WORKSHOP/ ALL ISSUES ADDRESSED/ CAN GO DIRECTLY TO SITE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: `
Vin/serial No: L4B2MG1077'

Lot 266 - 2001 WINGET HT DUMPER



Condition: RUNNING/ VERY NEAT LITTLE DUMPER/ BEEN THROUGH WORKSHOP/ ALL ISSUES ADDRESSED/ CAN GO DIRECTLY TO SITE
Qty: 1
LOCATION: BOKSBURG
Mileage: NOT VISIBLE
Vin/serial No: L4B2MG1078'

Lot 267 - START OF TSUKULU POLOKWANE ASSETS



Lot 268 - TADANO TL-200M 20-TON MOBILE CRANE



Condition: SOLD AS IS
Vin/serial No: KV208520005'
Reg_no: CLL296L
Engine_no: 6D22186649'
LOCATION: POLOKWANE

Lot 269 - LIEBHERR LTM1080/1 80-TON MOBILE CRANE



Vin/serial No: W09474000YEL05210'
Reg_no: HHC310L
LOCATION: POLOKWANE

Lot 280 - START OF CTC PLANT ASSETS



Lot 281 - 1993 CAT D9N



Colour: YELLOW
Condition: GOOD CONDITION -
RUNNER/ WELL MAINTAINED AND
HONEST/ WORK READY
Qty: 1
Mileage: 22 000 HOURS
No_of_keys: 1

Lot 285 - START OF PMG ASSETS



Lot 286 - CAT 320D EXCAVATOR WITHOUT BREAKER ATTACHMENT



Colour: YELLOW
Condition: NON RUNNER/ OIL
MARKS ALL OVER BODY/ NO
BUCKET/ SEATS TORN/
WINSCREEN CRACKED/ DENTS/
SCRATCHES/ RUST VISIBLE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: 1

Lot 290 - START OF SOUTH 32 ASSETS



Lot 291 - EPIROC COPCO BOOMER UNDERGROUND DRILLING JUMBO



Condition: NON-RUNNER
STRIPPED/ BADLY RUSTED/ ALL
WHEELS MISSING/ BADLY
STRIPPED/ DENTS/ SCRATCHES/
SOME PANELS BENT
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 292 - ATLAS COPCO BOLTEC H235



Condition: NON-RUNNER
STRIPPED/ BADLY RUSTED/ BADLY
STRIPPED/ DENTS/ SCRATCHES/
SOME PANELS BENT/ NO WHEELS
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 293 - EPIROC BOOMER 282 PARTS (LOCATED AT AUCOR JHB)



Condition: PARTS
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 294 - SANDVIK DS310 BOLTING BOOM ASSEMBLY



Condition: REFURBISHED
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 295 - CATERPILLAR COUNTERWEIGHTS



Condition: BADLY RUSTED
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 296 - ASSORTED LOT FRONT DOZER BLADE WITH ARMS/ CYLINDERS/ INDUSTRIAL HOSE REEL



Colour: YELLOW
Condition: BADLY RUSTED
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 297 - CATERPILLAR COUNTERWIGHT/ BALLAST WEIGHT



Colour: YELLOW
Condition: BADLY RUSTED
Qty: 1
LOCATION: HOTAZEL (INFRA) -
NORTHERN CAPE

Lot 305 - START OF CORPORATE SELLER



Lot 306 - BR2712908 DIFFERENTIAL 773F



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 307 - BR2712908 DIFFERENTIAL 773F



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 308 - BR2826916 DIFFERENTIAL 725



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 309 - LHD7830PX STD GRP - AXLE FRONT (LHD3518PX)



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 310 - BR1124068 DIFFERENTIAL 824G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 311 - BR1124068 DIFFERENTIAL 824G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 312 - BR2327554 WHEEL STATION 980G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 313 - BR2327554 WHEEL STATION 980G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 314 - BR2327554 WHEEL STATION 980G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 315 - BR1537520 TRANSMISSION 994D



Qty: 2
LOCATION: BOKSBURG - GAUTENG

**Lot 320 - START OF PTSSA GODDARD ASSET
(ZIMBABWE - BULAWAYO)**



Lot 321 - 2018 CAT 390F EXCAVATOR



Condition: RUNNER/
WINDSCREEN HAS PROTECTION
SHIELD FITTED/COUNTERWEIGHT/
BOOM/ STICK AND BUCKET ALL
PRESENT/ REMOVED FOR
TRANSPORT/ FULL SERVICE
HISTORY

LOCATION: BULAWAYO -
ZIMBABWE

Mileage: 21762 HOURS

Vin/serial No:
CAT0390FCGAY20117'

Engine_no: TXW04766'

Lot 325 - START OF CORPORATE SELLER ASSETS



Lot 326 - CAT 320 D EXCAVATOR



Qty: 1

LOCATION: WELLINGTON -
WESTERN CAPE

**Lot 327 - 20 TON HYDRALIC ROTATING DEMOLISION
AND SORTING GRAPPLE**



Qty: 1

LOCATION: WELLINGTON -
WESTERN CAPE

Lot 328 - SCELATON BUCKET



Qty: 1

LOCATION: WELLINGTON -
WESTERN CAPE

Lot 329 - CAT 320 GP BUCKET



Qty: 1

LOCATION: WELLINGTON -
WESTERN CAPE

Lot 330 - CAT 320D H LINK



Qty: 1

LOCATION: WELLINGTON -
WESTERN CAPE

Lot 335 - START OF BABCOCK PLANT ASSETS



Lot 336 - 2001 LIEBHERR LTM 1030/2 30 TON ROUGH TERRAIN CRANE



Condition: FRONT LEFT WHEEL REMOVED FOR REPAIR / WHEEL NUTS PRESENT/SMOKE ON COLD STARTUP/ SMOKE CLEARS UPON ENGINE BEING WARM AND UPON REVING/CRANE HAS JUST COME FROM A WORKING SITE

Vin/serial No: W092625001EL05800'

Reg_no: DN49CVGP

LOCATION: BABCOCK DEPOT - JET PARK

Lot 337 - TADANO A/T ATF100-5 MOBILE CRANE



Condition: FRONT LEFT WHEEL AND DRUM REMOVED/FRONT RIGHT WHEEL AND DRUM REMOVED/SECOND REAR AXLE RHS WHEEL AND COMPLETE HUB REMOVED/THIRD REAR AXLE RHS WHEEL AND COMPLETE HUB REMOVED/LHS FRONT AND REAR OUTRIGGER ARMS REMOVED/OUTRIGGER HYDRAULIC LINES REMOVED/LEFT REAR OUTRIGGER LEAKING/STEERING CYLINDERS LEAKING/DIFFERENTIALS SHOW NO VISIBLE DAMAGE/ENGINE FAN REMOVED/TURBO AIR PIPE REMOVED/TURBO OUTPUT PIPE REMOVED/TURBO LEFT OPEN TO THE ELEMENTS/RADIATOR HOSE REMOVED/DRIVING CAB PARTIALLY STRIPPED/CRANE CAB PARTIALLY STRIPPED

Vin/serial No: WFN5RTPN7Y4090013'

Reg_no: DP92FMGP

LOCATION: BABCOCK DEPOT - Elandsfontein