Africa's favourite auctioneers

October Mining Auction 5 : Unsold Assets

Venue: --

Friday, 30 October @ 17h00

Lot 1 - SUBJECT TO CONFIRMATION PERIOD



Lot 5 - START OF THARISA MINERALS



Lot 6 - 2008 LIEBHERR R9150 EXCAVATOR | TH229



Colour: WHITE
Condition: NON RUNNER/ NO BUCKET / NO TRACKS/ MACHINE HYDRAULIC PIPES HAVE BEEN STRIPPED/ ENGINE HAS BEEN STRIPPED MISSING ENGINE COVERS
Qty: 1
Mileage: 26514
No_of_keys: NOT VISIBLE

Lot 7 - 2008 LIEBHERR R9150 EXCAVATOR | TH245



Colour: WHITE
Condition: NON RUNNER/ MACHINE IS IN A POOR CONDITION HYDRAULIC OIL LEAKS ON MACHINE TURN TABLE/ ENGINE COVERS ARE STRIPPED INTERIOR IS STRIPPED
Qty: 1
Vin/serial No: WLHZ1133CZE038006'
LOCATION: OLD ASSEMBLY YARD

Lot 8 - CAT 3512B ENGINE | TH51



Qty: 1
Vin/serial No: 2100263138'
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 9 - ASSORTED TRACKS (ITR C31 LH) | TH57



Qty: 2
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 10 - ASSORTED TRACKS (ITR C31 LH) | TH58



Qty: 2
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 11 - LIEBHERR R 964 EXCAVATOR BOOM | TH503



LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Lot 12 - LIEBHERR R 964 EXCAVATOR BOOM | TH502



LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Lot 13 - LIEBHERR R 964 EXCAVATOR STICK | TH500



LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 14 - ESCO SUPER V V69SD SERIES BUCKET TOOTH TIPS | TH534



Qty: 9
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 15 - ESCO V71SD MINING TOOTH TIPS | TH535



Qty: 15
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 16 - MTG STARMET TOOTH TIPS | TH537



Qty: 5
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 17 - (CAT) EXTREME DUTY COUPLERS / ADAPTERS | TH540



Qty: 8
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 18 - CRAWLER CRANE OR DRILL RIG UNDERCARRIAGE TRACK FRAME COMPONENTS | TH541



Qty: 4
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 19 - EXCAVATOR QUICK COUPLERS | TH542



Qty: 2
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 20 - HYDRAULIC CYLINDERS FOR D55 AND EPIROC T45 | TH548



Qty: 8
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 21 - PROTECTION ARCH FOR EPIROC T45 | TH552



Qty: 1
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 22 - TRACK PROTECTION LINERS/HOOD AND PROTECTION ARCH FOR EPIROC T45 | TH553



Qty: 2
LOCATION: MINING STORES - MARIKANA - NORTH WEST

Lot 23 - 2008 TEREX 'FLAT TOP' COMEDIL TOWER CRANES (DISMANTLED) | TH13



Qty: 2
Vin/serial No: G7708022'
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 24 - 1X ELECTRICAL MOTOR (30KW)/ 4X VIBRATING MOTORS | P22



Qty: 5
LOCATION: OSMI STOCK - MARIKANA - NORTH WEST

Lot 25 - ELECTRICAL MOTOR GUARDS | TH40



Qty: 2
LOCATION: SALVAGE YARD - MARIKANA - NORTH WEST

Lot 26 - PILOT CRUSHTEC GTL02 LIGHTING PLANT | TH254



Qty: 1
LOCATION: OLD ASSEMBLY YARD - MARIKANA - NORTH WEST

Lot 27 - PERISTALTIC HOSE PUMPS | P227



Qty: 2
LOCATION: VULCAN PLANT - MARIKANA - NORTH WEST

Lot 28 - ACTUATED KNIFE GATE VALVES | P222



Qty: 3
LOCATION: VULCAN PLANT - MARIKANA - NORTH WEST

Lot 29 - PUMP FRAME | TH453



Qty: 1
LOCATION: OSMI STOCK - MARIKANA - NORTH WEST

Lot 30 - CONCRETE GUIDES | TH469



Qty: 1
LOCATION: OSMI STOCK - MARIKANA - NORTH WEST

Lot 31 - LOT ASSORTED IDLER FRAMES | TH474



Qty: 1
LOCATION: OSMI STOCK - MARIKANA - NORTH WEST

Lot 32 - STEEL FRAMES | TH477



Qty: 5
LOCATION: OSMI STOCK - MARIKANA - NORTH WEST

Lot 33 - LOT ASSORTED KITCHEN FURNITURE/ TAPS/ MICROWAVES/ STOVES/ & HYDRAULIC PUMPS | TH60



Qty: 1
LOCATION: SALVAGE YARD

Lot 34 - START OF SIYANDA BAKGATLA



Lot 35 - 1974 MOREWEAR S/AXLE DROPSIDE SEMI TRAILER



Condition: FAIR CONDITION
Qty: 1
Vin/serial No: 9797'
Reg_no: CZB907L
Engine_no: -'

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 36 - GST DRILL RIG



Colour: YELLOW
Condition: NON RUNNER/RUST MARK AND SCRATCHES ALL OVER THE BODY/ NO BATTERY/ HYDRAULIC PIPES LOOSE/ ENGINE COVER LOOSE/INTERRIOR STRIPPED/
Mileage: 768
No_of_keys: NO KEY
Vin/serial No: NO TAG '

Lot 37 - FERMEL UTILITY VEHICLE



Colour: YELLOW
Condition: NON RUNNER/NO ENGINE/ NO TRANSMISSION/ HYDRAULIC PIPES LOOSE /RUST MARK AND SCRATCHES ALL OVER THE BODY/
No_of_keys: NO KEY
Vin/serial No: NO TAG '
LOCATION: 4 SOUTH SHAFT - NORTHAM - LIMPOPO

Lot 38 - 2010 FERMEL UTILITY VEHICLE (CASSETTE LOADER)



Colour: YELLOW
Condition: POOR CONDITION/ INTERIOR STRIPPED/ ENGINE COVERS MISSING/ NO BATTERY/ COMPONENTS STRIPPED/
Qty: 1
No_of_keys: NO KEYS
Vin/serial No: NO TAG'

Lot 39 - GST DILL RIG



Colour: YELLOW
Condition: NON RUNNER/ NO BATTERY/ BACK GRILL MISSING/ DRILLING ATTACHMENT MISSING/ NO SEAT/ SCRATCHES ALL OVER THE BODY
Qty: 1
Mileage: 899
No_of_keys: NO KEY

Lot 40 - LOT ASSORTED HEAVY DUTY TYRES



Qty: 1
LOCATION: SALVAGE YARD - NORTHAM - LIMPOPO

Lot 41 - LIQUID RESISTANCE STARTER



Qty: 1
LOCATION: MORTIMER CONCETRATOR - NORTHAM - LIMPOPO

Lot 42 - HEADBOARD OMNI 89 450 x 150



Qty: 1
LOCATION: MAIN STORES - NORTHAM - LIMPOPO

Lot 43 - VIBRATING MOTOR



Qty: 1
LOCATION: Richard SHAFT - NORTHAM - LIMPOPO

Lot 44 - VENTILATION PIPES



Qty: 29
LOCATION: DECLINE 1

Lot 45 - VENTILATION PIPES



Qty: 35
LOCATION: DECLINE 1

Lot 46 - LAYFLAT FORCE INDUCTION AND SPIRAL FORCE INDUCTION



Qty: 1
LOCATION: MAIN STORES

Lot 47 - START OF SIBANYE STILL WATER ASSETS



Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 48 - LOT ASSORTED PIPES & FITTINGS/ MUCKING MACHINE GEAR/ MUCKING MACHINE SPARES/ SCAFOLLDING/ EXLDUDING THE BUFFER



Qty: 1
LOCATION: KUSELEKA SHAFT - RUSTENBURG - NORTH WEST

Lot 49 - START OF SOUTH 32 ASSETS



Lot 50 - SANDVIK DS310 BOLTING BOOM ASSEMBLY



Condition: REFURBISHED
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 51 - CATERPILLAR COUNTERWEIGHTS



Condition: BADLY RUSTED
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 52 - ASSORTED LOT FRONT DOZER BLADE WITH ARMS/ CYLINDERS/ INDUSTRIAL HOSE REEL



Colour: YELLOW
Condition: BADLY RUSTED
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 53 - CATERPILLAR COUNTERWIGHT/ BALLAST WEIGHT



Colour: YELLOW
Condition: BADLY RUSTED
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 54 - LOT ASSORTED STEEL PIPES/ STEEL POLES/ WOODEN POLES



Condition: STEEL POLES RUSTED/ WOODEN POLES CRACKED AND SOME DAMAGED
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 55 - STEEL ELECTRICAL OR CONTROL CABINET



Colour: GREY
Condition: RUST VISIBLE
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 56 - LOT ASSORTED SERVER/ NETWORK RACK CABINETS



Colour: BLACK
Condition: FAIR CONDITION
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 57 - LOT ASSORTED STEEL SHELVES



Colour: GREY
Condition: SOME SHELVES ARE DENTED
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 58 - LOT ASSORTED LARGE HDPE MECHANICAL COMPRESSION FITTINGS



Colour: BLACK/ BLUE
Condition: FAIR CONDITION
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 59 - LOT ASSORTED LARGE-DIAMETER FLANGED WATER-PIPELINE FITINGS AND VALVES



Colour: BLUE
Condition: RUST VISIBLE
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 60 - LOT ASSORTED LARGE STEEL SPIRAL VENTILATION DUCTS AND DUCT CONNECTORS



Colour: GREY
Condition: RUST VISIBLE
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Lot 61 - LOT ASSORTED PROTECTIVE TRANSPORT/ STORAGE RING/ PERMA SEAT



Colour: WHITE
Condition: BADLY RUSTED ON FRAME
Qty: 1
LOCATION: HOTAZEL (INFRA) - NORTHERN CAPE

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 62 - START OF DEPARTMENT OF CORRECTIONAL SERVICES ASSETS



Lot 63 - 2009 FORD FOCUS 2.0 Si A/T



Colour: WHITE
Condition: NON RUNNER/ ENGINE STRIPPED AND DISMANTLED/ SCRATCHES/ DENTS/ CHIPMARKS ON PAINT
Qty: 1
Mileage: 396482 KM
No_of_keys: 2

Lot 64 - 2011 FORD FOCUS 1.8 Si 5Dr



Colour: WHITE
Condition: NON-RUNNER/ ENGINE STRIPPED/ GEARBOX STRIPPED/ MINOR SCRATCHES AND DENTS
Qty: 1
Mileage: 289943 KM
No_of_keys: 1

Lot 65 - START OF SEDIBENG IRON ORE ASSETS



Lot 66 - DOOSAN DX700LC EXCAVATOR



Condition: RUNNER/ HYDRAULIC OIL LEAKS/ BUCKET RUSTED/ SCRATCHES/ DENTS/ RUST VISIBLE/ SIDE WALKS BENT/ FAIR CONDITION
Qty: 1
Vin/serial No: DWGCECANKD1005037'
LOCATION: POSTMASBURG

Lot 67 - START OF PMG ASSETS



Lot 68 - CAT 320D EXCAVATOR WITHOUT BREAKER ATTACHMENT




Colour: YELLOW
Condition: NON RUNNER/ OIL MARKS ALL OVER BODY/ NO BUCKET/ SEATS TORN/ WINSCREEN CRACKED/ DENTS/ SCRATCHES/ RUST VISIBLE
Qty: 1
Mileage: NOT VISIBLE
No_of_keys: 1

Lot 69 - START OF THUNGELA RESOURCES (MAFUBE COAL) ASSETS



Lot 70 - LOT ASSORTED UNROLLED CONVEYOR BELT/ STEELCORE AND PLY LON



Condition: USED
Qty: 1
LOCATION: OVERLAND 5 AND PLANT - MIDDELBURG - MPUMALANGA

Lot 71 - LOT ASSORTED UNROLLED STEELCORE CONVEYOR BELTS



Condition: USED
Qty: 1
LOCATION: RLT - MIDDELBURG - MPUMALANGA

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 72 - START OF CORPORATE SELLER ASSETS



Lot 73 - TADANO TL-200M 20-TON MOBILE CRANE



Condition: SOLD AS IS
Vin/serial No: KV208520005'
Reg_no: CLL296L
Engine_no: 6D22186649'
LOCATION: POLOKWANE

Lot 74 - LIEBHERR LTM1080/1 80-TON MOBILE CRANE



Vin/serial No: W09474000YEL05210'
Reg_no: HHC310L
LOCATION: POLOKWANE

Lot 75 - START OF TEICHMANN ASSETS



Lot 76 - 2011 ASPHALT CIBER PLANT UACF 17P-2 ADVANCED

Condition: WORKING CONDITION
Qty: 1
LOCATION: BOKSBURG
Mileage: 928 HOURS

Lot 77 - START OF CTC PLANT ASSETS



Lot 78 - 1993 CAT D9N



Colour: YELLOW
Condition: GOOD CONDITION - RUNNER/ WELL MAINTAINED AND HONEST/ WORK READY
Qty: 1
Mileage: 22 000 HOURS
No_of_keys: 1

Lot 79 - START OF PTSSA (GODDARD) ASSETS



Lot 80 - 2018 CAT 390F EXCAVATOR



Condition: RUNNER/ WINDSCREEN HAS PROTECTION SHIELD FITTED/COUNTERWEIGHT/ BOOM/ STICK AND BUCKET ALL PRESENT/ REMOVED FOR TRANSPORT/ FULL SERVICE HISTORY
LOCATION: BULAWAYO - ZIMBABWE
Mileage: 21762 HOURS
Vin/serial No: CAT0390FCGAY20117'
Engine_no: TXW04766'

Lot 81 - START OF BABCOCK PLANT ASSETS



Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 82 - TADANO A/T ATF100-5 MOBILE CRANE



Condition: FRONT LEFT WHEEL AND DRUM REMOVED/FRONT RIGHT WHEEL AND DRUM REMOVED/SECOND REAR AXLE RHS WHEEL AND COMPLETE HUB REMOVED/THIRD REAR AXLE RHS WHEEL AND COMPLETE HUB REMOVED/LHS FRONT AND REAR OUTRIGGER ARMS REMOVED/OUTRIGGER HYDRAULIC LINES REMOVED/LEFT REAR OUTRIGGER LEAKING/STEERING CYLINDERS LEAKING/DIFFERENTIALS SHOW NO VISIBLE DAMAGE/ENGINE FAN REMOVED/TURBO AIR PIPE REMOVED/TURBO OUTPUT PIPE REMOVED/TURBO LEFT OPEN TO THE ELEMENTS/RADIATOR HOSE REMOVED/DRIVING CAB PARTIALLY STRIPPED/CRANE CAB PARTIALLY STRIPPED
Vin/serial No: WFN5RTPN7Y4090013'
Reg_no: DP92FMGP
LOCATION: BABCOCK DEPOT - Elandsfontein

Lot 83 - START OF CORPORATE SELLER 1 ASSETS



Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 84 - 1991 MERCEDES BENZ 1114 FLAT DECK TRUCK



Colour: WHITE
Condition: STRUGGLES TO START/IGNITION BYPASSED/VISIBLE WELDING WORK DONE/STONE CHIP MARKS ON WINDSCREEN/FRONT BUMPER DENTED AND SCRATCHED/MULTIPLE BODY PANELS PAINT DAMAGED/MULTIPLE BODY PANELS SCRATCHED AND DENTED/VISIBLE REPAIR AND SPRAY WORK/VISIBLE LOOSE WIRES ON PASSENGER SIDE DASHBOARD/RADIO REMOVED/BOTH INTERIOR DOOR HANDLE BROKEN/GEAR LEVER DAMAGED/DRIVER SEAT TORN/NO SPARE WHEEL/DASHBOARD COVER REMOVED/1990 MODEL REGISTERED IN 1991
Qty: 1
Mileage: 624553
No_of_keys: 1

Lot 85 - 2018 MERCEDES-BENZ ACTROS 2645LS/33 A/T DOUBLE AXLE HORSE



Colour: WHITE
Condition: OIL LEAK/BRAKE PADS FAULTY/SERVICE DUE/GEARBOX WARNING LIGHT ON/FRONT INDICATORS NOT WORKING/WINDSCREEN CRACKED/GRILLE DAMAGED/FRONT BUMPER DAMAGED/MULTIPLE BODY PANELS DENTED AND SCRATCHED/PASSENGER SIDE DOOR DAMAGED/PASSENGER SIDE SIDE STEP DAMAGED/TYRES WORN
Qty: 1
Mileage: 468037
No_of_keys: 2

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 86 - 2017 MERCEDES-BENZ ACTROS 2641 LS/33 DD DOUBLE AXLE HORSE



Colour: WHITE
Condition: 21 DAY PAPER DELAY/OIL LEAK/CLUSTER FAULTY NOT SHOWING KILOMETRES/DIESEL TANK DENTED/SERVICE DUE/BATTERY COVER REMOVED/LANE ASSIST DEFECTIVE WARNING LIGHT ON/RIGHT BRAKE LAMP DEFECTIVE WARNING LIGHT ON/GRILLE CRACKED/BUMPERS DAMAGED/MULTIPLE BODY PANELS SCRATCHED AND DENTED/VISIBLE REPAIR AND SPRAY WORK/DRIVER SIDE SUN VISOR DAMAGED/DRIVER SIDE ARM REST DAMAGED/CHEVRON TRIM CRACKED AND LOOSE/BACK COVER REMOVED FROM PASSENGER SIDE VIEW MIRROR/SEATS TORN/TYRES WORN
Qty: 1
Mileage: UNKNOWN
No_of_keys: 1

Lot 87 - 2013 FREIGHTLINER ARGOSY 90 CUM 500 NG T/T C/C



Colour: WHITE
Condition: OIL LEAKS/ENGINE WARNING LIGHT ON/ABS AND BRAKE PADS WARNING LIGHTS ON/MULTIPLE BODY PANELS SCRATCHES AND DENTS/WINDSCREEN CRACKED/VISIBLE POOR REPAIR AND SPRAY WORK/PASSENGER FUEL TANK STEPS DAMAGED/PASSENGER INTERIOR DOOR HANDLE DAMAGED/SEATS TORN AND LOOSE/DRIVERS SIDE STEP POOR REPAIRED/DASHBOARD COMPARTMENT POOR REPAIRED/INTERIOR TRIMS DAMAGED/DRIVERS SIDE CAP DAMAGED
Qty: 1
Mileage: 962946
No_of_keys: 1

Lot 88 - START OF CORPORATE SELLER 2 ASSETS



Lot 89 - BR2712908 DIFFERENTIAL 773F



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 90 - BR2826916 DIFFERENTIAL 725



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 91 - BR1124068 DIFFERENTIAL 824G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 92 - BR1124068 DIFFERENTIAL 824G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 93 - BR2327554 WHEEL STATION 980G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 94 - BR2327554 WHEEL STATION 980G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 95 - BR2327554 WHEEL STATION 980G



Qty: 1
LOCATION: BOKSBURG - GAUTENG

Lot 96 - BR1537520 TRANSMISSION 994D




Qty: 2
LOCATION: BOKSBURG - GAUTENG

Lot 97 - START OF CORPORATE SELLER 3 ASSETS



Lot 98 - CAT 320 D EXCAVATOR



Qty: 1
LOCATION: WELLINGTON - WESTERN CAPE

Lot 99 - 20 TON HYDRALIC ROTATING DEMOLISION AND SORTING GRAPPLE



Qty: 1
LOCATION: WELLINGTON - WESTERN CAPE

Lot 100 - SCELATON BUCKET



Qty: 1
LOCATION: WELLINGTON - WESTERN CAPE

Lot 101 - CAT 320 GP BUCKET



Qty: 1
LOCATION: WELLINGTON - WESTERN CAPE

Lot 102 - CAT 320D H LINK



Qty: 1
LOCATION: WELLINGTON - WESTERN CAPE

Lot 103 - START OF CORPORATE SELLER 4 ASSETS



Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 104 - COBRA HOSE REELS: NS200 (15 METER HOSES; 3/8 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 4
LOCATION: GQEBERHA - EASTERN CAPE

Lot 105 - COBRA HOSE REELS: NS200 (15 METER HOSES; 3/8 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 5
LOCATION: GQEBERHA - EASTERN CAPE

Lot 106 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 107 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 108 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 109 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 110 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 111 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Aucor will not be held responsible for any errors in description. All goods are sold with no duty to repair.

Aucor.com

Lot 112 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 113 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE

Lot 114 - COBRA HOSE REELS: NS600 (15 METER HOSES; 3/4 HOSE)



Colour: BLUE
Condition: BRAND NEW
Qty: 6
LOCATION: GQEBERHA - EASTERN CAPE